orm 3160-5	UNITED STATES	N.M. OII CO	ons. Division
une 1990)	DEPARTMENT OF THE INTERIOR	P.O. Box 198	Rudent Russey No. 1004 0195
	BUREAU OF LAND MANAGEMENT	P.U. DUX 190	Expires: March 31, 1993
		Hobbs, NM 8	824 mase Designation and Serial No.
			LC 029410A
	SUNDRY NOTICES AND REPORTS ON WEL	LS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposa	is to drill or to deepen or reentry to a different	reservoir.	
Use "APPLICATION I	FOR PERMIT for such proposals		7. If Unit or CA, Agreement Designation
Type of Well	SUBMIT IN TRIPLICATE	·····	
X Oil Gas IN	IJECTION		a vivame or lease & well
Well Well Other		MCA Unit	
			Well #211 9. /API#
CONOCO, INC.		·	30 025 00763
	nd, Texas 79705-4500,915 686-5424 915 684-638	81	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R.,	M., or Survey Description)	<u> </u>	Maljamar Grayburg San Andres
			11. County or Parish, State
Surface: 660' FSL & 660' FEL TD: Sec 29, TI7S, R32E, Unit Letter P			
			Lea, NM
2 CHECK APPROPRIAT	E BOX(s) TO INDICATE NATURE OF NO	OTICE, REPORT, OR	OTHER DATA
TYPE OF SUBMISSK		TYPE OF ACTION	
Notice of Intent	Aband	lonment	Change of Plans
	Recon	npletion	New Construction
X Subsequent Report		ing Back	Non-Routine Fracturing
Subsequent report		g Repair	Water Shut-Off
	Casing Casing	y rtepan	
First About served			Conversion to Injection
Final Abandonment I	Notice Alterin	g Casing	
Final Abandonment I	Notice Alterin		Conversion to Injection Conversion to Injection Dispose Water Note: Report results of multiple completion on Well
	Notice Alterin	ng Casing tubing & casing integrity test	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Starting any proposed work. If well is
 3. Describe Proposed or Completed Ope directionally drilled, give subsurface 6-22-98: MIRU. SION. 6-23-98: Removed well out of hole. Rig 6-24-98: RIH, circulate pump truck & I & POOH w/tut 	Notice Atterin Atterin Atterin X Check t Selecations (Clearly state all pertinent defails, and give pertinent da be locations and measured and true vertical depths for all mark lhead, installed new wellhead & BOP, rigg gged down scan-a-log, SION. Ide packer fluid, latched on to packer, remo ran casing integrity test. Removed wellhead bing, SION. dro-tester, RIH hydrotesting tubing to 5000 & installed wellhead, rigged up pump truc	ng Casing hubing & casing integrity test ites, including estimated date of ters and zones pertinent to this w ged up scan-a-log, ins wed BOP & installed w ad & installed BOP, re 0#. Rigged down. Late k, ran casing integrity	Conversion to Injection Dispose Water (Note: Report reaches of multiple completion on Well Completion or Recompletion Report and Log term.) Starting any proposed work. If well is work.)* spected tubing wellhead, rigged up bleased on/off tool sched on to packer
 3. Describe Proposed or Completed Ope directionally drilled, give subsurfact 6-22-98: MIRU. SION. 6-23-98: Removed well out of hole. Rig 6-24-98: RIH, circulate pump truck & I & POOH w/tut 6-25-98: Rigged up hy removed BOP 6-29-98: Put well on in 	Notice	ng Casing hubing & casing integrity test ites, including estimated date of ters and zones pertinent to this w ged up scan-a-log, ins wed BOP & installed w ad & installed BOP, re 0#. Rigged down. Late k, ran casing integrity	Conversion to Injection Conversion to Injection Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is work.)* spected tubing wellhead, rigged up eleased on/off tool sched on to packer y test - good test. ECORIC: SCD.) GARY GOURLI
 3. Describe Proposed or Completed Ope directionally drilled, give subsurfact 6-22-98: MIRU. SION. 6-23-98: Removed well out of hole. Rig 6-24-98: RIH, circulate pump truck & I & POOH w/tut 6-25-98: Rigged up hy removed BOP 	Notice	ng Casing hubing & casing integrity test ites, including estimated date of ters and zones pertinent to this w ged up scan-a-log, ins wed BOP & installed w ad & installed BOP, re 0#. Rigged down. Late k, ran casing integrity	Conversion to Injection Dispose Water New Papor reads of multiple completion on Well Completion or Recompletion Report and Log farm.) Starting any proposed work. If well is work.)* spected tubing wellhead, rigged up eleased on/off tool sched on to packer y test - good test. EDGHD Dispose SGD.) GARY GOURLI CORIG. SGD.)
 Describe Proposed or Completed Ope directionally drilled, give subsurfact 6-22-98: MIRU. SION. 6-23-98: Removed well out of hole. Rig 6-24-98: RIH, circulate pump truck & I & POOH w/tut 6-25-98: Rigged up hy removed BOP 6-29-98: Put well on in 	Notice	ng Casing hubing & casing integrity test hies, including estimated date of ters and zones pertinent to this w ged up scan-a-log, ins wed BOP & installed v ad & installed BOP, re 0#. Rigged down. Lat ck, ran casing integrity	Conversion to Injection Conversion to Injection Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is work.)* spected tubing wellhead, rigged up eleased on/off tool sched on to packer y test - good test. ECORIC: SCD.) GARY GOURLI
 Describe Proposed or Completed Ope directionally drilled, give subsurfact 6-22-98: MIRU. SION. 6-23-98: Removed well out of hole. Rig 6-24-98: RIH, circulate pump truck & I & POOH w/tut 6-25-98: Rigged up hy removed BOP 6-29-98: Put well on in 	Notice	ng Casing hubing & casing integrity test hies, including estimated date of ters and zones pertinent to this w ged up scan-a-log, ins wed BOP & installed v ad & installed BOP, re 0#. Rigged down. Lat ck, ran casing integrity	Conversion to Injection Dispose Water exer Report reads of multiple completion on Well Completion or Recompletion Report and Log term.) Starting any proposed work. If well is work.)* spected tubing wellhead, rigged up eleased on/off tool sched on to packer y test - good test. CORIG. SCID.) GARY GOURLI CORIG. SCID.) GARY GOURLI Date 7-3I-98
 Describe Proposed or Completed Ope directionally drilled, give subsurfact 6-22-98: MIRU. SION. 6-23-98: Removed well out of hole. Rig 6-24-98: RIH, circulate pump truck & I & POOH w/tut 6-25-98: Rigged up hy removed BOP 6-29-98: Put well on in 	Notice	ng Casing hubing & casing integrity test hies, including estimated date of ters and zones pertinent to this w ged up scan-a-log, ins wed BOP & installed v ad & installed BOP, re 0#. Rigged down. Lat ck, ran casing integrity	Conversion to Injection Dispose Water New Report reads of multiple completion on Well Completion or Recompletion Report and Log farm.) Starting any proposed work. If well is work.)* spected tubing wellhead, rigged up eleased on/off tool sched on to packer y test - good test. EDGHD Dispose SGD.) GARY GOURLI CORIG. SGD.)

~

ъ.

*See Instruction on Reverse Side

D/C

V



6-25-98 LONDIO MCA 211 . UNIT LETTER P SEC. 29-T175-R32E

Pool UNIT 6 Arnof Somelle Arnold Sorrells