

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instruction
verse side)DATE
a reForm approved.
Budget Bureau No. 42-R1421.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029410A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)At surface
1295' JSL + 1345' JSL of Sec. 29, T-17S
R-32E, Lea Co., N.M.

7. UNIT AGREEMENT NAME

MCA Unit Repr.

8. FARM OR LEASE NAME

MCA Unit 1

9. WELL NO.

172

10. FIELD AND POOL, OR WILDCAT

Maly G-SA Repr.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 29, T-17S, R32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3932' J.

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

Deepen 50' + Stimulate ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

It is proposed to frac OH 3846-3988' w/30,000 gals
prod. wtr containing 25# "Adomite Aqua" + 40 #
Quar/1000 gals + 60,800# 20-40 sand in 2 equal
stages.

With 6 7/8" bit & jet out drill out 50' to new
TD of 4050'. Treat new zone as follows:
Pump in 1500 gals prod. water containing 50#
"Adomite Aqua" + 40# Quar/1000 gals. Follow
w/5000 gal 20% LSTHF acid containing silt
suspension additives.
Run prod. equipment & place well on prod.

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Youley

TITLE

Administrative Rep.

DATE

3-10-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

USGS(5) MCA(3) File

*See Instructions on Reverse Side