

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE*
(Other: Instructio
verse aide)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit Sty 1</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>167</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1980' F5L & 660' FEA - Unit Letter I</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G-5A</i>
14. PERMIT NO. <i>30-025-00775</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>S30, 17, 32</i>
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work started on 3/28/88. Jet wash & drill out to 3875'. Hit junk. Mill out & cut new hole to 3897'. Kicked away from junk. Spot 20 bbls 15% HCL-NE-FE from 3780'-3889'. Resin pack w/48 bbls. Drill out from 3342'-3802'. Tag-metal. Mill from 3802'-3907'. Drill to 4061'. G1H w/5 1/2' csg to 3976'. Set w/150 csg of 50/50 Poz mix class "C" cement. D O cmt to 70L at 3133'. G1H w/ tie back. Drill out float & cement to 3974'. Perf w/2 js pf from 3898'-3938'. Acidize & sand frac. Perf 6th zone 3726'-3806' & Upper 7th zone 3818'-3870' acidize & inhibit. Run producing equipment & place on production. Work completed on 6/15/88.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*
(The space is for Federal or State office use)

TITLE *Administrative Supervisor*

DATE *July 14, 1988*

APPROVED BY
SIGNATURES OF APPROVAL, IF ANY:

TITLE *[Signature]*

DATE *[Signature]*

*See instructions on Reverse Side

BLM - Caswell (6) OX4(1) FPCO(1) ZL