

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other: instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit Bty 1</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>108</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>660' FNL & 660' FEL - Unit Letter A</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G-SA</i>
14. PERMIT NO. <i>30-025-00783</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>30-175-32 E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) *Convert to Cased Hole*

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 6/27/88. MURU. POOH w/ rods & pump. Clean out & jet wash to 3963'. Run OH caliper from 3333'-3960'. Test csq to 2000 psi. Pickled Hbg w/ 23 bbls 15% HCL-NE-FE acid. Spot 35 bbls acid from 3600'-3963'. Resin pack OH w/ 37 bbl. G1H w/ bit & tag top of resin pack at 3465'. DO 3465' to TD. Deepen to 4000'. Underream 3730'-3963'. Set 5 1/2" liner at 4000' w/ 120 sk 50/50 Pozmix class "C" cement. G1H w/ bit & tag TOL at 3238'. DO cement 3798'-3955'. Perf 9th zone w/ 1 jspf 3932'-3972' & acidize. Perf 7th zone w/ 2 jspf 3784'-3858' & acidize. Perf 6th zone 3664'-3738' & acidize. Run 2 1/8" Hbg. Run producing equipment & place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED *DE FINNEY*

TITLE *Administrative Supervisor*

DATE *9/13/88*

This space for internal or State office use

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

SEP 19 1988

*See instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the State any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) OX4(1) FPCO(1) Lil.