N. M. OIL CONS. COMMISSION

Form 9-331 Dec. 1973 P. O. BOX 1980 HOBBS, NEW MEXICO 88240

Form Approved. Budget Bureau No. 42-R1424

Dec. 1973	-3484 241004 1101 17 114 14 14 14 14 14 14 14 14 14 14 14 14
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	LC-059001 (a)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	- C. II INDIAN, ALLOTTLE ON TRIBLINANCE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Oo not use this form for proposals to drill or to deepen or plug back to a different	.
eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
A	Pearsall A
1. oil gas well other injection well	9. WELL NO.
	- /
2. NAME OF COERATOR	10. FIELD OR WILDCAT NAME
3 ADDRESS OF APPRATOR. NIAL 000/10	Pearsall Queen
3. ADPRES BOX ART PAUDEs, N.M. 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	-1 · · · · · · · · · · · · · · · · · · ·
helow.)	Sec. 33, T-175, R-32E
AT SURFACE: 1980 FNL \$ 660 FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Lea NM
AT TOTAL DEPTH: 🗸	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<u>-1</u>
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	13. ELLEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	and took took took took took took
rest water shut-off 🔲 🔲 🗎 🔝	
RACTURE TREAT	
SHOOT OR ACIDIZE	Book of the second seco
REPAIR WELL	(NOTE: Report esults of multiple completion or zone
OULL OR ALTER CASING MAY	4 1983 change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES U	. & GAS
ABANDON*	
	NEW MEXICO
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stational including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones perting	ate all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and
MIRU 4-26-83. Circ hole w/9# brine	
VIKU 4-26-03. CITE HOLE W/ 1" DITHE	. 200 25 200, 20 A L
@ 2905'-2760'. Spot 25 sxs. cl.'c' ci	nt. 2320'-2175! WOC 4ns
Too Top of cont. @ 2219! SION. Perf.	w/4TSPF @ 1125! Set pkr

MIRLL 4-26-83. Circ hole w/ 4# brine. Spot 25 sks. Cl. C' cmt. 2320'- 2175! woc 4 hrs.

2905'-2760'. Spot 25 sks. cl. C' cmt. 2320'- 2175! woc 4 hrs.

Tag Top of cmt. @ 2219'. SION. Perf. w/4JSPF @ 1125! Set pkr.

21030'. Circ. thru perfs back to surface. Rel. pkr. Set cmt. retainer

21030'. Pump 100 sks. cl. C' cmt. thru perfs. Spot 15' cmt on top

of retainer. Circ. trace cmt. to surface. Spot 25 sks. Surface plug.

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED WMO Suffer TITLE Administrative Supervisor	DATE 5/3/83
Origi Sadi Fine S. Dollar APPROVED BY CONDITIONS OF APPROVAL; IF ANY:	DATE

Install dry hole marker. Cut off dead men.

TO SER LOSS