Form 9-331	บทเา ี ∙ รา	TATES	SUBMIT IN TRIPLIC	Form approved. Budget Bureau No. 42-R1424.
May 1963)	DEPARTMENT OF		(Other instructions on e-	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL		18.0	11-059000
CI	JNDRY NOTICES AND	·	WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use t	this form for proposals to drill or to Use "APPLICATION FOR PER	n deepen or plug back MIT—" for such propos	to a different reservoir.	
OIL GAS OTHER				7. UNIT AGREEMENT NAME
Continentel oil O.				MCA Unit
3. ADDRESS OF OPERA	1460 Hobb	s, n.m	9KiCO	9. WELL NO. 226
See also space 17		-	÷	Michael G-SA Repu
660'F	NL and 660	FWLO	fSec34	11. SEC. ST., R., M., OR BLK. AND SURVEY OF AREA  SEC 34. 7-175, R-3
14. PERMIT NO.	15. ELEVATION	S (Show whether DF, RT,	GR, etc.)	12. COUNTY OF PARISH 13. STATE  Lea // My
		x To Indicate Natu	re of Notice, Report, or O	ther Data
16.	Check Appropriate Bo			
16.	Check Appropriate Bo			ENT REPORT OF:
	NOTICE OF INTENTION TO:	<u> </u>		ENT REPORT OF:
TEST WATER SHO	NOTICE OF INTENTION TO:	CASING	SUBSEQU	را
TEST WATER SHO	NOTICE OF INTENTION TO:  UT-OFF PULL OR ALTER O	CASING	SUBSEQU WATER SHUT-OFF	REPAIRING WELL
TEST WATER SH	NOTICE OF INTENTION TO:  UT-OFF PULL OR ALTER O	CASING	SUBSEQU WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPAIRING WELL  ALTERING CASING  ABANDONMENT*
TEST WATER SHO FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL (Other)	NOTICE OF INTENTION TO:  UT-OFF PULL OR ALTER ( MULTIPLE COMPI ABANDON* CHANGE PLANS	EASING	SUBSEQU  WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (Note: Report results Completion or Recomple	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  of multiple completion on Well etion Report and Log form.)
FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL (Other)	NOTICE OF INTENTION TO:  UT-OFF PULL OR ALTER ( MULTIPLE COMPI ABANDON* CHANGE PLANS	EASING	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomple	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  of multiple completion on Well etion Report and Log form.) including estimated date of starting any
TEST WATER SHO FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL (Other)  17. DESCRIBE PROPOSE proposed work nent to this wo	NOTICE OF INTENTION TO:  UT-OFF PULL OR ALTER ( MULTIPLE COMPLETED OPERATIONS (Clearly If well is directionally drilled, gi	EASING	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomple	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  of multiple completion on Well etion Report and Log form.)

Set pocker at 3870' and froc'd 0/ w/30000 gel.

Set pocker at 3870' and 60,000 # 20/40 Sond

Thatled produced water and 60,000 # 20/40 Sond

Completed - 11-3-72

\*See Instructions on Reverse Side

U. S. GEOLOGIONE SOLVEY HOBBS, NEW MEXICO

c mcA-3 File

PETT ED

NO. 21 TO OIL COUSERVACIOR COMM. HORBS, N. M.