

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-125-01209
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-2118
7. Lease Name or Unit Agreement Name	
State G	
8. Well No.	2
9. Pool name or Wildcat	
Saunders Permian Upper Penn	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER Injection

2. Name of Operator
CHARLES B GILLESPIE JR

3. Address of Operator
P.O. BOX 8 Midland, Tx. 79702

4. Well Location
Unit Letter C : 660 Feet From The north Line and 1980 Feet From The west Line
Section 3 Township 15-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Perforated 4 holes @ 3100' squeezed 30 sacks cement W.O.C. tagged plug @ 2989'
- (2) Perforated 4 holes @ 297', unable to pump into formation, pressured up to 2000 psi, spotted 25 sacks cement across perforations W.O.C. tag plug @179'
- (3) Spotted 15 sacks cement @ surface, set P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE 11-20-93

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Jack Griffin TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SAD

RECEIVED

JUN 17 1924

OLD NEW YORK
OFFICE