

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01212 ✓
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-2118
7. Lease Name or Unit Agreement Name	STATE G
8. Well No.	5
9. Pool name or Wildcat	ryffell Saunders Permian Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4186' GR 4199 DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CHARLES B. GILLESPIE JR.
3. Address of Operator P.O. BOX 8 Midland, Tx. 79702	4. Well Location Unit Letter H : 2120 Feet From The North Line and 660 Feet From The East Line Section 3 Township 15-S Range 33-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4186' GR 4199 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Lead hole w/mud
- (2) Cut 5 1/2 casing POOH @ 4716
- (3) Spot 30 sacks cement @ 5 1/2 stub 4776' W.O.C. tag plug @ 4672'
- (4) Spot 30 sacks cement @ 8 5/8 shoe 4285' W.O.C. Tag plug @ 4173'
- (5) Cut 8 5/8 casing POOH w/700'
- (6) Spot 55 sacks cement @ 8 5/8 stub 700' W.O.C. Tag plug @ 639'
- (7) Spot 80 sacks cement @ 13 3/8 shoe 345' W.O.C. Tag plug @ 246'
- (8) spot 15 sacks cement @ surf. Set P&A marker

work began 4-29-93 completed 5-15-93

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE 5-21-93

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE NOT 20 1994

CONDITIONS OF APPROVAL, IF ANY: