- Submit 3 Copies o Appropriate Energ District Office	State of New Me: y, Minerals and Natural Re		
.U. BOX 1980, HODDE, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.
OSTRICT II O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE
<u>ISTRICT III</u> 100 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. E-2118
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
Type of Well: OIL CAS WELL X WELL			
	OTHER		State 'G'
Name of Operator Charles B. Gillespie	, Jr.		8. Well No. 5
Address of Operator			9. Pool name or Wildcat
P. O. Box 8 Midla Well Location	nd, Texas 79702		Saunders Permo Upper Penn
Section 3 Tow	Vaship <u>155</u> Rar 10. Elevation (Show whether L 4186' DF	OF, RKB, RT, GR, etc.)	NMPM Lea County
	minte Por to Indicate N	Jature of Notice P	
1. Check Approp NOTICE OF INTENTI	priate Box to Indicate N ON TO:		SEQUENT REPORT OF:
NOTICE OF INTENT			-
		SUB	SEQUENT REPORT OF:
	ON TO: LUG AND ABANDON	SUB REMEDIAL WORK	SEQUENT REPORT OF:
NOTICE OF INTENTI	ON TO: LUG AND ABANDON	SUB REMEDIAL WORK COMMENCE DRILLING	SEQUENT REPORT OF:
NOTICE OF INTENTI	ON TO: LUG AND ABANDON	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora	SEQUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB rily Abandon
NOTICE OF INTENTI RFORM REMEDIAL WORK PL IMPORARILY ABANDON CH ULL OR ALTER CASING THER: 2 Describe Proposed or Completed Operations (Cle work) SEE RULE 1103. 5/91: Set cast iron bridge	ON TO: UG AND ABANDON	SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora d give periment dates, inclu-	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ADD ABANDONMENT CASING PLUG AND ABANDONMENT CASING CASI
NOTICE OF INTENTI RFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING THER: 2 Describe Proposed or Completed Operations (Cle work) SEE RULE 1103. 15/91: Set cast iron bridge hole in 5 1/2" casin 18/91: Drilled retainer and	ON TO: LUG AND ABANDON HANGE PLANS Corrig state all pertiment details, and plug at 9590'. S g at 5806' with 24	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora define periment dates, inclu-	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ADD ABANDONMENT CASING PLUG AND ABANDONMENT CASING CASI
NOTICE OF INTENTI RFORM REMEDIAL WORK PL MPORARILY ABANDON CH ULL OR ALTER CASING THER: 2 Describe Proposed or Completed Operations (Cla work) SEE RULE 1103. 5/91: Set cast iron bridge hole in 5 1/2" casin 8/91: Drilled retainer and minutes - tested ok. 9/91: Drilled on bridge pl	ON TO: LUG AND ABANDON HANGE PLANS Dariy state all pertiment details, and plug at 9590'. S g at 5806' with 24 cement. Pressure ug at 9590'. 5 1/	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give periment dates, inclu set cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll	SEQUENT REPORT OF: ALTERING CASING ALTERING AND ABANDONMENT ALTERING CASING A
NOTICE OF INTENTI RFORM REMEDIAL WORK PL MPORARILY ABANDON CH ULL OR ALTER CASING THER: 2 Describe Proposed or Completed Operations (Cla work) SEE RULE 1103. 5/91: Set cast iron bridge hole in 5 1/2" casin 8/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3	ON TO: LUG AND ABANDON HANGE PLANS Dariy state all pertiment details, and plug at 9590'. S g at 5806' with 24 cement. Pressure ug at 9590'. 5 1/ /8" tubing stuck a	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give periment dates, inclu et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2	SEQUENT REPORT OF: ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING AL
NOTICE OF INTENTI RFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING THER: 2 Describe Proposed or Completed Operations (Cle work) SEE RULE 1103. 5/91: Set cast iron bridge hole in 5 1/2" casin 8/91: Drilled retainer and minutes - tested ok. 9/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off	ON TO: LUG AND ABANDON HANGE PLANS Dug at 9590'. S g at 5806' with 24 cement. Pressure ug at 9590'. 5 1/ /8" tubing stuck a 2 3/8" tubing at 6	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora degive periment dates, include et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'.	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING COPNS. PLUG AND ABANDONMENT COMENT JOB PLUG AND ABANDON COMENT JOB PLUG AND ABANDON PLUG AND ABANDON COMENT JOB PLUG AND ABANDON C
NOTICE OF INTENTI ERFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING CH ULL OR ALTER CASING CH Work) SEE RULE 1103. 15/91: Set cast iron bridge hole in 5 1/2" casin 18/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper	ON TO: LUG AND ABANDON HANGE PLANS Dug at 9590'. S g at 5806' with 24 cement. Pressure ug at 9590'. 5 1/ /8" tubing stuck a 2 3/8" tubing at 6 sub, jars, 3 1/2"	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora degive periment dates, include et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING COPNS. PLUG AND ABANDONMENT COMENT JOB PLUG AND ABANDON COMENT JOB PLUG AND ABANDON PLUG AND ABANDON COMENT JOB PLUG AND ABANDON C
NOTICE OF INTENTI RFORM REMEDIAL WORK PL MPORARILY ABANDON C ULL OR ALTER CASING C ULL OR ALTER CASING C THER: 2 Describe Proposed or Completed Operations (Cla work) SEE RULE 1103. 5/91: Set cast iron bridge hole in 5 1/2" casin 8/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper Jarred on 2 3/8" tub 22/91: Ran free point. Tot stuck at 6060'. Pul	ON TO: LUG AND ABANDON HANGE PLANS ANGE PLANS LUG ANGE PLANS LUG ANGE PLANS LUG at 9590'. S g at 5806' with 24 cement. Pressure Ug at 9590'. 5 1/ /8" tubing stuck a 2 3/8" tubing at 6 sub, jars, 3 1/2" ing at 6018' - no al depth of free p led overshot. Rec	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give perinent dates, inclu set cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars movement. oint survey 94 overed 2 1/2'	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING COPNS. PLUG AND ABANDONMENT COMENT JOB PLUG AND ABANDON COMENT JOB PLUG AND ABANDON PLUG AND ABANDON COMENT JOB PLUG AND ABANDON C
NOTICE OF INTENTI RFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING CH PL 2 Describe Proposed or Completed Operations (Cla work) SEE RULE 1103. 5/91: Set cast iron bridge hole in 5 1/2" casin 8/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper Jarred on 2 3/8" tub 22/91: Ran free point. Tot stuck at 6060'. Pul (Tubing collapsed wh 23/91: Ran flat bottomed mi from 6020'-6022'.	ON TO: LUG AND ABANDON HANGE PLANS ANGE PLANS LUG at Pertiment details, and plug at 9590'. S g at 5806' with 24 cement. Pressure Ug at 9590'. 5 1/ /8" tubing stuck at 2 3/8" tubing at 66 sub, jars, 3 1/2" ing at 6018' - no al depth of free p led overshot. Rec ile releasing over 11 to dress off 2	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora drive periment dates, inclu et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars movement. oint survey 94 overed 2 1/2' shot). 3/8" tubing.	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MEMENT JOB rily Abandon rily Abandon ding estimated date of starting any proposed iner at 5680'. Squeezed cement. casing to 500# for 15 apsed. " casing collapsed at and 2 7/8" tubing. 12'. 2 3/8" tubing still
NOTICE OF INTENTI ERFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING CH THER: 2 Describe Proposed or Completed Operations (Cla work) SEE RULE 1103. 15/91: Set cast iron bridge hole in 5 1/2" casin 18/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper Jarred on 2 3/8" tub 22/91: Ran free point. Tot. stuck at 6060'. Pul (Tubing collapsed wh 23/91: Ran flat bottomed mi from 6020'-6022'.	ON TO: LUG AND ABANDON HANGE PLANS HANGE PLANS Diriv state all pertiment details, and plug at 9590'. S g at 5806' with 24 cement. Pressure Ug at 9590'. 5 1/ /8" tubing stuck a 2 3/8" tubing at 6 sub, jars, 3 1/2" ing at 6018' - no al depth of free p led overshot. Rec ile releasing over 11 to dress off 2	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give perinent dates, inclu et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars movement. oint survey 94 overed 2 1/2' shot). 3/8" tubing.	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ADDITION
NOTICE OF INTENTI ERFORM REMEDIAL WORK PL EMPORARILY ABANDON CH JUL OR ALTER CASING CH Work) SEE RULE 1103. 15/91: Set cast iron bridge hole in 5 1/2" casin 18/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper Jarred on 2 3/8" tub 22/91: Ran free point. Tot stuck at 6060'. Pul (Tubing collapsed wh 23/91: Ran flat bottomed mi from 6020'-6022'. I hereby certify that the information above is true and components SIONATURE Market M	ON TO: LUG AND ABANDON HANGE PLANS HANGE PLANS Diriv state all pertiment details, and plug at 9590'. S g at 5806' with 24 cement. Pressure Ug at 9590'. 5 1/ /8" tubing stuck a 2 3/8" tubing at 6 sub, jars, 3 1/2" ing at 6018' - no al depth of free p led overshot. Rec ile releasing over 11 to dress off 2 Note to the best of my knowledge and 12 Plate to the best of my knowledge and 12	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give perinent dates, inclu et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars movement. oint survey 94 overed 2 1/2' shot). 3/8" tubing.	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING COPNS. PLUG AND ABANDONMENT CEMENT JOB TIly Abandon Comparing any proposed Ting estimated date of starting any proposed Comparing to 500# for 15 Comparing to 500# to 15 Comparing to 50 Compa
NOTICE OF INTENTI ERFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING CH Work) SEE RULE 103. 15/91: Set cast iron bridge hole in 5 1/2" casin 18/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper Jarred on 2 3/8" tub 22/91: Ran free point. Tot stuck at 6060'. Pul (Tubing collapsed wh 23/91: Ran flat bottomed mi from 6020'-6022'. I bereby certify that the information appres is true and com SHONATURE David W. Hasting TYPE OR PRINT NAME David W. Hasting	ON TO: LUG AND ABANDON HANGE PLANS HANGE PLANS Dug at 9590'. S g at 5806' with 24 cement. Pressure Ug at 9590'. 5 1/ /8" tubing stuck a 2 3/8" tubing at 66 sub, jars, 3 1/2" ing at 6018' - no al depth of free p led overshot. Rec ile releasing over 11 to dress off 2 where to the best of my knowledge and 12 provide to the best of my knowledge and 12 pro	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give perinent dates, inclu et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars movement. oint survey 94 overed 2 1/2' shot). 3/8" tubing.	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ADDITION
NOTICE OF INTENTI ERFORM REMEDIAL WORK PL EMPORARILY ABANDON CH ULL OR ALTER CASING CH 2. Describe Proposed or Completed Operations (Cla work) SEE RULE 1103. 15/91: Set cast iron bridge hole in 5 1/2" casin 18/91: Drilled retainer and minutes - tested ok. 19/91: Drilled on bridge pl 20/91: Ran free point. 2 3 6060'). Backed off 21/91: Ran overshot, bumper Jarred on 2 3/8" tub 22/91: Ran free point. Tot. stuck at 6060'. Pul (Tubing collapsed wh 23/91: Ran flat bottomed mi from 6020'-6022'.	ON TO: LUG AND ABANDON HANGE PLANS HANGE PLANS HANG	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CH OTHER: Tempora d give perinent dates, inclu et cement reta 5 sx class 'C' tested 5 1/2" 2" casing coll t 6060' (5 1/2 018'. drill collars movement. oint survey 94 overed 2 1/2' shot). 3/8" tubing.	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING COPNS. PLUG AND ABANDONMENT CEMENT JOB TIly Abandon Comparing any proposed Ting estimated date of starting any proposed Comparing to 500# for 15 Comparing to 500# to 15 Comparing to 50 Compa