

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

| |
|---|
| WELL API NO. 30-025-01213 ✓ |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. E-2118 |
| 7. Lease Name or Unit Agreement Name State "G" |
| 8. Well No. 6 |
| 9. Pool name or Wildcat Saunders Pemo-Penn |

| | |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | |
| 2. Name of Operator Charles B. Gillespie, Jr. | |
| 3. Address of Operator P.O. Box 8 Midland, TX 79702 | |
| 4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>15-S</u> Range <u>33-E</u> NMPM <u>Lea</u> County <u></u> | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4189' GR, 4202' DF</u> | |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load hole with mud.
2. Spot 100' cement plug at 5 1/2" casing stub at ^{6045 on top of stub} ~~5913~~' with 50' in and 50' out and tag.
3. Spot 100' cement plug across 8 5/8" shoe at 4230' and tag.
4. Cut off and pull 8 5/8" casing from approximately 800'.
5. Spot 100' cement plug at 8 5/8" casing stub with 50' in and 50' out and tag.
6. Spot 100' cement plug across 13 3/8" shoe at 297'.
7. 15 sx. cement plug at surface.
8. Weld 4" marker to surface pipe and clean location.

THIS NOTICE WAS RECEIVED 24
HOURS PRIOR TO THE BEGINNING OF
DRILLING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William R. Crow TITLE Exploration Manager DATE 3/18/93

TYPE OR PRINT NAME William R. Crow

TELEPHONE NO. (915) 683-1765

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

MAR 31 1993

APPROVED BY DISTRICT MANAGER TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: