

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01223
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-2118
7. Lease Name or Unit Agreement Name	State G
8. Well No.	11
9. Pool name or Wildcat	Saunders Permian Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Charles B. Gillespie, Jr.	
3. Address of Operator P.O. Box 8 Midland, Tx. 79702	
4. Well Location Unit Letter B : 800 Feet From The North Line and 1980 Feet From The East Line Section 4 Township 15-S Range 33-E NMPM Lea N.M. County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) spot 25 sacks cement plug @ 9580, W.O.C. Tag @ 9357'
- (2) load hole w/mud
- (3) spot 25 sacks cement plug @ 6500'
- (4) Cut & pull 5 1/2 casing @ 4666'
- (5) Spot 30 sacks cement @ 5 1/2 stub 4716, W.O.C. tag 4616'
- (6) spot 35 sacks cement @ 8 5/8 shoe 4225' W.O.C. Tag 4116'
- (7) cut & pull 8 5/8 casing @ 692'
- (8) spot 55 sacks cement plug @ 8 5/8 stub 742' W.O.C. tag 639'
- (9) spot 75 sacks cement plug @ 13 3/8 shoe 346' W.O.C. no tag @ 13 3/8 shoe
- (10) respot 75 sacks cement plug @ 13 3/8 shoe 346' W.O.C. tag @ 243'
- (11) spot 15 sacks surf., plug & ser P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE \_\_\_\_\_  
TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

(This space for State Use)

APPROVED BY Jack Griffin TITLE \_\_\_\_\_ DATE \_\_\_\_\_