

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01234
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-819
7. Lease Name or Unit Agreement Name State "M" Com
8. Well No. 2
9. Pool name or Wildcat Saunders Permo Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4199 DF

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Charles B. Gillespie
3. Address of Operator P.O. Box 8 Midland, Texas 79702
4. Well Location Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line Section 10 Township 15-S Range 35-E 33 NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4199 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP @ 9500'. Capped w/5 sx cmt.
- 2) Spotted 25 sx cmt plug @ 6500'.
- 3) Cut off casing @ 3271'. Pulled casing.
- 4) Spotted 25 sx cmt plug @ 4285'.
- 5) Spotted 55 sx cmt plug @ 3321'. WOC. Tagged @ 3194'.
- 6) Shot sqz holes @ 345'. Sqz w/ 50 sx cmt. Did not tag.
- 7) Shot sqz holes @ 280'. Could not pump into perfs.
- 8) Spotted 35 sx cmt. Plug @ 280'. WOL. Tagged @ 170'.
- 9) Put 15 sx plug @ surface. Well P&A on 2-22-94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin Widner TITLE Production Manager DATE 11-21-95

TYPE OR PRINT NAME Kevin Widner

TELEPHONE NO. (915) 683-176

(This space for State Use)

APPROVED BY Carmy W. Hill TITLE State Engineer DATE MAY 02 1997

CONDITIONS OF APPROVAL, IF ANY: