

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 32-025-01234
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-819
7. Lease Name or Unit Agreement Name State "M"
8. Well No. 2
9. Pool name or Wildcat <i>Sanders Perm Upper Perm</i>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Charles B. Gillespie, Jr.	
3. Address of Operator P.O. Box 8 Midland, Texas 79702	
4. Well Location Unit Leader <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>10</u> Township <u>15-S</u> Range <u>3-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4199 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP above perms at 9500'. Cap with cement.
- 2) Spot 25 sx plug at 6500'.
- 3) Cut and pull 5-1/2" casing at approximately 6000'.
- 4) Spot 100' plug at 5-1/2" stub. 50' in 50' out.
- 5) Spot 100' plug at 8-5/8" shoe at 4235'.
- 6) Spot 100' plug at 13-3/8" shoe at 295'.
- 7) Put 15 sx plug at surface.
- 8) Weld on 4" dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin Widner TITLE Production Manager DATE 2-8-94
TYPE OR PRINT NAME Kevin Widner TELEPHONE NO. (915)683-1765

(This space for State Use)

APPROVED BY [Signature] TITLE _____ DATE _____

FEB 08 1994

WELL NAME: STATE "M" #2

SURF CGG: 13- $\frac{3}{8}$ " @ 295'

TOL @ SURF

INTER CGG: 8- $\frac{5}{8}$ " @ 4235

TOL @ ?

PROD CGG / LINER: 5- $\frac{1}{2}$ " @ 10,100'

TOL @ 7303

DETS: 9790-10057

TUBING: 264 JTS (NO TAC)

RODS: 99 ($\frac{7}{8}$ "
219 ($\frac{3}{4}$ "

REMARKS: CIBP SET @ 9500'

** NEED TO CAP CIBP W/CMT **

** HAVE PRIDE SHOW THAT THEY SET CIBP **

RECEIVED

RECEIVED

NOV 11 1961