STATE OF NEW MEXICO WERGY AND MINERALS DEPARTMENT

NA. AT COPIES SECEIVES		
		
HOITHBUTTON	1	
BANTA FE		
/ ILE		
U.\$.G.\$.		
LAND OFFICE		
OPPRATOR		İ

OIL CONSERVATION DIVISION

NO. OF COPIES SECESTARY	OIL COMBLICATI		
DISTRIBUTION	P. O. BOX	2088	Form C-103 Revised 10-1-73
BANTAFE	SANTA FE, NEW I	MEXICO 87501	K641260 10-1-12
PILE	,		5a. Indicate Type of Lease
U.\$.G.\$.			State X Fee
LAND OFFICE			
OPPRATOR			5. State Off & Gas Lease No.
CLINIDAN NO.	TICES AND REPORTS ON W	/FIIS	
(DO NOT USE THIS FORM FOR PROPOSALS	TICES AND REPORTS ON W	IN TO A DIFFERENT RESERVOIR.	
USE APPELLEADING FOR			7. Unit Agreement Name
GAS C	TA Injection W	lell	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ien.		8. Farm or Lease Name
Charles B. Gi	llospio Ir		State M Com.
Charles D. Gl.	rieshie, or.		
ress of Operator			9. Well No.
P.O. Box 8 M	idland, Texas 797	02	# 5
cation of Well		•	10. Field and Pool, or Wildcat
	Nomen	1000	Saundana Parma Pann
HIT LETTER	FEET FROM THE NOTLI	_ LINE AND TOU FEET FR	· Saunders Permo-Penn
ME Westline, SECTION	10 TOWNSHIP 155	RANGE 33E NMI	···
			- XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show whether D	F, RT, GR, etc.)	12. County
	4201 DF		Lea
Charl Asso	-A-1	ture of Notice, Report or (Other Data
	-		NT REPORT OF:
NOTICE OF INTENT	TION TO:	SUBSEQUE	NI REPORT OF:
		<u></u>	
DAM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
ORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
_		OTHER Set bridge p.	lug above injection 🛚 🛣
		interval	
THER			

Set bridge plug at 9650'. 1.)

- Dumped two sacks cement on top of bridge plug. 2.)
- 3.) Loaded casing with KCL water and tested to 500#.

		of my knowledge and helief.		· · · · · · · · · · · · · · · · · · ·
I hereby certify that the information above is true and	complete to the bes	t of my allowings and nemer.		
" Jarel / botton	TITLE	Engineer	DATE	12/29/82
ORIGINAL SIGNED BY			JAI	V 3 1002
JEHRY SEXTON	717LE		0/1/ BATE	1983
DOTRICT TOURS				-