

Attachment C-103  
Gulf Oil Corporation  
Sams State No. 1  
Report on Plugging and Abandoning

1. Cut off 7" casing at 9,000' and pulled same.
2. Heavy mud from 10,200' to 9,020'.
3. Spotted cement plug from 9,020' to 8,940'. 26 sacks cement.
4. Cut off 9-5/8" casing at 1,500' and pulled same.
5. Heavy mud from 8,940' to 4,284'.
6. Spotted cement plug from 4,284' to 4,158'. 50 sacks cement.
7. Heavy mud from 4,158' to 1,545'.
8. Spotted cement plug from 1,545' to 1,457'. 51 sacks cement.
9. Heavy mud from 1,457' to 341'.
10. Spotted cement plug from 341' to 315'. 30 sacks cement.
11. Heavy mud from 315' to 25'.
12. Spotted cement plug from 25' to 0' and set 4" marker extending 4' above ground level. 20 sacks cement.