

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.
LG 1387

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ P&A

Name of Operator

Yates Petroleum Corporation

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE East LINE, SECTION 17 TOWNSHIP 15S RANGE 33E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Sams YC State

9. Well No.

1

10. Field and Pool, or Wildcat
Undesignated

11. Elevation (Show whether DF, RT, GR, etc.)

4221' GR

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JGB ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:
Set a CIBP in 7" casing at about 2100' w/35' cement.
Set plug at 1550-1450' - 100' or 20 sacks cement.
Set plug at 20' to surface w/10 sacks cement.

Clean location and install P&A marker.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Eddie W. Seay

TITLE Production Supervisor

DATE 2-27-84

Eddie W. Seay

Oil & Gas Inspector

TITLE

DATE

FEB 29 1984

CONDITIONS OF APPROVAL, IF ANY: