

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01271
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-259
7. Lease Name or Unit Agreement Name Phillips State
8. Well No. 1
9. Pool name or Wildcat Kemnitz Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4148' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Fina Oil and Chemical Company
3. Address of Operator PO Box 10887, Midland, Tx 79702	4. Well Location Unit Letter I : 1980 Feet From The South Line and 1980 Feet From The East Line Section 25 Township 16S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4148' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Set CIBP @ 10,725' and cap w/ 5 sx.	Data: 5-1/2" CSA 11,030'; cmt w/ 270 sx; TOC at 9650' by temp. survey.
2) Spot 10 sx @ 7725-7625 and tag.	8-5/8" CSA 4553'; cmt w/ 1500 sx; circ
3) Cut csg @ 4600' and pull.	13-3/8" CSA 364'; cmt w/ 400 sx; cir.
4) Spot 30 sx at 4600-4500' and tag.	perfs: 10,772-10,804'
5) Spot 30 sx at 1700-1600' top of salt.	10,811-10,829'
6) Spot 30 sx at 415-315' and tag.	top of salt at 1650'
7) 10 sx top plug.	

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Jim Redfearn</u>	TITLE <u>Sr. Staff Engineer</u>	DATE <u>3/10/94</u>
TYPE OR PRINT NAME <u>Jim Redfearn</u>	TELEPHONE NO. <u>(915) 688-0600</u>	

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR  
MAR 14 1994