

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO **HOBBS OFFICE O.C.C.**
WILDERNESS CONSERVATION COMMISSION

APR 29 11 32 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 1671	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Cactus Drilling Company		8. Farm or Lease Name Union A State
3. Address of Operator P O Box 2068, Hobbs, New Mexico		9. Well No. 1
4. Location of Well UNIT LETTER 0 1650 FEET FROM THE East LINE AND 330 FEET FROM THE South LINE, SECTION 33 TOWNSHIP 16 South RANGE 33 East NMPM.		10. Field and Pool, or Wildcat Sannal
15. Elevation (Show whether DF, RT, GR, etc.) 4198 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On verbal authority from Mr. Joe D. Ramey, plugging of well performed in the following manner on 4/23/66:

15 sx cement plug set 4400-4485; 25 sx cement plug set 1465-1553 (in and out of 5 1/2" casing w/shoot-off point 1503'; 25 sx cement plug set 275-312 (in and out of surface casing shoe); 10 sx cement plug set at surface. All intervals between cement plugs filled with mud.

Lease is cleared of all equipment, surface returned to natural contour and appropriate well marker set to identify the location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Geo. W. Baker TITLE **Vice President** DATE **4/28/66**

APPROVED BY Leslie H. Clements DATE JUN 1 1966
CONDITIONS OF APPROVAL, IF ANY: