

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 8962	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A - Re-Entry		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name TexGulf AEN State
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>17S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Sanmal - Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4155' top of tubing head		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-2-87 - Drilled and washed to 1237'. Hole caving. Drilled and washed to 1520'.
4-5-87 - Received verbal permission from Ray Smith, NMOCD, Hobbs, NM, to P&A well as follows:

Plug #1 1520-1420' w/35 sacks Class "C"
Plug #2 430-330' w/50 sacks Class "C" across 13-3/8" shoe.
Tag plug at 337'.
Plug #3 50' to Surface w/25 sacks Class "C".
Clean location. Installed dry hole marker.
Plugging completed 4-5-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Santa Doo dunt TITLE Production Supervisor DATE 4-8-87
APPROVED BY Lyle F. Turnaclyff TITLE OIL & GAS INSPECTOR DATE DEC 30 1988
CONDITIONS OF APPROVAL, IF ANY:

Posted 4-10-87 S

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED