

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Murphy H. Baxter		Address 509 Midland National Bank Bldg. Midland, Texas				
Lease State "18-B"	Well No. 7	Unit Letter G	Section 18	Township T-17-S	Range R-33-E	
Date Work Performed 11-8-58	Pool Maljamar			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☒ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spudded in @ 7:00 P.M. November 7, 1958. Drilled 12 1/4" hole to 292'. Ran & cemented 9 Joints (275.91') of 8 5/8" 24# J-55 8RT new seamless Spang casing @ 287.91' with 150 sax HOC regular 4% Gel cement. Cement circulated. WOC 24 hours. Nippled up blow out preventers and tested casing with 1000# for 30 minutes. Casing tested OK.

Witnessed by M. D. Lewis	Position Production Supt.	Company Murphy H. Baxter
------------------------------------	-------------------------------------	------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY


ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		


RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

Approved by 
Title
Date

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name 
Position
Petroleum Engineer
Company
Murphy H. Baxter