

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-025-01489
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
2149

7. Lease Name or Unit Agreement Name:
Caprock Maljamar Unit

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other - Injection

2. Name of Operator
The Wiser Oil Company

8. Well No. #205

3. Address of Operator
P.O. Box 2568 Hobbs, New Mexico 88241

9. Pool name or Wildcat
Maljamar Grayburg San Andres

10. Well Location

Unit Letter L : 1650 feet from the SOUTH line and 1059' feet from
the WEST line

Section 19 Township 17S Range 33E NMPL LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4071' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

11 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU. POH with production equipment. TIH with csg. Scraper. Set CIBP @ 4144'
- Dump 25 sxs cement on plug.
- Circulate abandonment mud.
- Set 25 sx cement plug @ 1360' and 2480'.
- Perforate casing @ 400' and circulate cement to surface in the casing annulus.
- POH to 50' and set cement plug to surface.
- Install dry hole marker.
- Clean location.

THE COMMISSION MUST BE NOTIFIED 24
HOURS BEFORE THE BEGINNING OF
PLUGGING OPERATIONS FOR THE CIBP
TO BE APPROVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G. M. Jones TITLE : Superintendent DATE 12/6/99

Type or print name: G. M. Jones

(This space for State use) ORIGINAL SIGNED BY

APPROVED BY GARY WINK TITLE FIELD REP II DATE DEC 28 1999

Conditions of approval

IC

✓