

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-01496

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

8. Well No.

69

9. Pool name or Wildcat

Maljamar Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL ☐

GAS ☐

WELL ☐

WELL ☐

OTHER

WIW

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico

4. Well Location

Unit Letter K : 1650 Feet From The South Line and 2310 Feet From The West Line

Section 20 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4201' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/15/97 MIRU Ram Well Service. NU BOP. Release on/off tool. POH w/2-3/8" IPC tbg. RIH w/R-4 pkr. & 2-3/8" work string. Set pkr. @ 4015'. Pressure immediately went to 1000 PSI on tbg. 0# on csg.

7/21/97 Circulate hole clean. Trip tbg. LD pkr. RIH w/camera.

7/22/97 Attempt camera job w/no success.

7/23/97 LD work string. RIH w/retrieving tool on 2-3/8" IPC tbg. Attempt catch perma latch pkr. w/no success.

7/24/97 Circulate & POH w/pkr. RIH w/5-1/2" Baker J-Lok pkr., on/off tool w/1.5" profile & 131 jts. 2-3/8" IPC tbg. Set pkr. @ 4097'. Released on/off tool. ND BOP. Install WH. Pump pkr. fluid. Latch on pkr. Place well back on injection. Test casing to 480 PSI. Copy of pressure chart attached. Performed/witnessed by Richard w/Bar Treating.

11/20/01 Test casing to 390 PSI (Copy of pressure chart attached. Performed/witnessed by Nick Jimenez with Gandy Corporation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mary Jo Turner

TITLE

Production Tech II

DATE

November 24, 2001

TYPE OR PRINT NAME

Mary Jo Turner

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

TITLE

DATE

B.A.R. Treating
Well # 69
Cmu

7-29-97

Richard E. Meads.