

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>	<p>7. Unit Agreement Name</p>	
<p>2. Name of Operator Union Oil of California</p>	<p>8. Farm or Lease Name Hume Queen Unit</p>	
<p>3. Address of Operator c/o Hobbs Pipe & Supply Company</p>	<p>9. Well No. #11</p>	
<p>4. Location of Well UNIT LETTER E, 1900 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 16-S RANGE 34-E NMPM.</p>	<p>10. Field and Pool, or Wildcat Hume Queen</p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4128'</p>		<p>12. County Lea</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

1. Propose to spot a 25 sx. cement plug from 3945'-3968'.
2. Propose to spot a 25 sx. cement plug at 5 1/2" casing stub at 1400'.
3. Propose to spot a 25 sx. cement plug at 8 5/8" casing shoe at 268'.
4. Propose to spot a 10 sx. cement plug at surface with marker.
5. Hole will be loaded with mud laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Hebrew* TITLE Agent DATE 10-5-70

APPROVED BY *Joe D. Hines* TITLE SEAL AREA, DISTRICT DATE 10-5-70

CONDITIONS OF APPROVAL, IF ANY: