NO. OF COPIES RECEIVED	(Form C-103		
		Supersedes Old C-102 and C-103		
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65		
SANTA FE				
FILE		5a. Indicate Type of Lease		
U.S.G.S.		State Fee XX		
LAND OFFICE		5, State Oil & Gas Lease No.		
OPERATOR				
· · · · · · · · · · · · · · · · · · ·				
(DO NOT USE THIS FORM F	UNDRY NOTICES AND REPORTS ON WELLS FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. PLICATION FOR PERMIT			
1.		7. Unit Agreement Name		
OIL X GAS WELL				
2. Name of Operator		8. Farm or Lease Name		
Hanson Oil	York			
3. Address of Operator		9. Well No.		
P O Box	1515, Roswell, New Mexico 88201	# 1		
the setting of Woll		10. Field and Pool, or Wildcat		
A. Location of well	660 FEET FROM THE South LINE AND 1980 FEET FROM	Wildcat		
UNIT LETTER	FEET FROM THE LINE AND FEET FROM			
Veet	, section township 16-S RANGE 34-E NMPM			
THE West LINE	, SECTION TOWNSHIP RANGE NMPM	*/////////////////////////////////////		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
<u> </u>		Lea AllIIIII		
^{16.} Cl	heck Appropriate Box To Indicate Nature of Notice, Report or O	ther Data		
NOTICE	OF INTENTION TO: SUBSEQUEN	IT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB			
	other <u>Re-complet</u>	<u></u>		
OTHER .				
OTHER		the second states and states and second states and		
17. Describe Proposed or Comp	leted Operations (Clearly state all pertinent details, and give pertinent dates, includir	ng estimated date of starting any proposed		
work) SEE RULE 1103.				

- 10-17-75 Fluid Level 800' from surface. Swabbed 15 bbls. water in 7 hrs., leaves 138 bbls. load to recover. Released pkr., pulled out of hole, run Howco EZ drill bridge plug on 2 7/8" tbg. Set Bridge plug @ 4234, dumped 10 sx. cement on top of plug.
- 10-18-75 Pulled out of hole w/ pkr., picked up Western Wireline Co., perforated 2 holes per foot w/ West Jet Magnum from 4100-26', total of 32 holes. Run Howco RTTS pkr. @ 4139'. Spotted 200 gal., 15% N.E. acid over perfs., pulled 3 jts. of tbg., set pkr. @ 4046'. Broke down formation 2000 PSI, acidized w/ 3000 gal. 15% N.E. acid @ 6 bbls. per min.. Average 2500 PSI. Dropped 40- 7/8" Ball Sealers. ISIP 2100, 15 min. 1600, total load 122 bbls.. Started swabbing, recovered 43 bbls. in 4½ hrs.. Fluid level 300' above seating nipple, leaves 79 bbls. to recover. Shut down.
- 10-21-75 Fluid level 1200' above seating nipple. Swabbed 7 bbls. in 1 hr., swabbed dry, made 1 run per hour, fluid level 50' above seating nipple. Rigged up Halliburton, fracted well w/12000 gal. gelled water, 8000# 20/40 sand, 7000# 10/20 sand @ 16bbls. per min. @ 3800 PSI, ISIP 2300, 5 min. 2200, 15 min. 2100. Shut in overnight.

18. I hereby certify that t	information	above is true and complet	e to the best of n	ny knowledge and belief.		
1/n	, W		Vice	President/Product	ion DATE	1/19/76
SIGNED		I I			•	
APPROVED BY			TITLE		DATE	

с	ONDITIONS	OF	APPROVAL,	١F	ANY
---	-----------	----	-----------	----	-----