Submit 3 Copies to Appropriate District Office	Energy, Minerals and Natur	w Mexico ral Resources Department	Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA' P.O. Bo		WELL API NO.
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Me	xico 87504-2088	30-025-01910 5. Indicate Type of Lease STATE X FEE
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lesse No.
			V-3931
( DO NOT USE THIS FORM FOR P DIFFERENT RES	TICES AND REPORTS ON ROPOSALS TO DRILL OR TO DE ERVOIR. USE "APPLICATION FO C-101) FOR SUCH PROPOSALS.	EPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OL. GAS WELL	() OTHER		Cities Service AQP State
2. Name of Operator			8. Well No.
YATES PETROLEUM CORPO	VKAIIUN		9. Pool name or Wildcat
<ol> <li>Address of Operator</li> <li>105 South 4th St., An</li> </ol>	tesia. NM 88210		Undesignated Morrow
4. Well Location			I UNGESTENALEG HUILUW
	4	heiher DF, RKB, RT, GR, etc.) (085' DF cate Nature of Notice F	Report, or Other Data
	•• •		
	ITENTION TO:	SUE	
	NTENTION TO: PLUG AND ABANDON		ALTERING CASING
	ITENTION TO:	SUE	BSEQUENT REPORT OF:
	NTENTION TO: PLUG AND ABANDON CHANGE PLANS	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C	BSEQUENT REPORT OF:
NOTICE OF IN PERFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON CHANGE PLANS 	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Finishe product wails, and give pertinent dates, incl	BSEQUENT REPORT OF: ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB ed drilling cement plugs, set X tion casing uding estimated date of starting any proposed
NOTICE OF IN PERFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state all periment det Washed and reamed com 10590-10695'. Hi Washed and reamed fr Circulated. TOOH.	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Finish product tails, and give pertinent dates, incl firom 10415-10590' it top of cement a rom 10829-10892'.	BSEQUENT REPORT OF: ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB ed drilling cement plugs, set X tion casing
NOTICE OF IN PERFORM REMEDIAL WORK	TD at 6:30 AM 2-20-9 17# S-95 LT&C (2230 17# J-55 LT&C (2230 17# S-95 LT&C (2230 17# J-55 LT&C (2230)	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Finisher product tails, and give pertinent dates, incl firom 10415-10590' it top of cement a rom 10829-10892'. ith bit. Resumed 97. Ran 328 joint .26'); 75 joints o .59'); 76 joints o 1897.14') (Total 1 at collar set at 1 d in two stages as 2 and .3% CD32 (yi	ALTERING CASING ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ed drilling cement plugs, set X tion casing uding estimated date of starting any proposed . Circulate and condition mud. t 10695'. Drilled cement plug Circulate. Washed and reamed drilling formation at 10:30 PM s of 5-1/2" 17# casing as follow f 5-1/2" 17# L-80 LT&C (3105.09' f 5-1/2" 17# L-80 LT&C (3119.37' 3460.45') of casing set at 3419'. Baffel plate set at follows: Stage 1: 1100 sacks eld 1.22, weight 14.4). PD
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS erations (Clearly state all periment det Washed and reamed com 10590-10695'. Hi Washed and reamed fr Circulated. TOOH. 500'. TOOH. TIH wi TD at 6:30 AM 2-20-9 17# S-95 LT&C (3108) 17# J-55 LT&C (2230) 1/2" 17# S-95 LT&C (1) set at 13459'. Float t at 9313'. Cemented . 3% BAIO, 1.3% FL6 Ingrand complete to the best of my knowle	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Finishe product tails, and give pertinent dates, incl firom 10415-10590' it top of cement a rom 10829-10892'. ith bit. Resumed 97. Ran 328 joint .26'); 75 joints o .59'); 76 joints o 1897.14') (Total 1 at collar set at 1 d in two stages as 2 and .3% CD32 (yi adge and belief. CO	ALTERING CASING ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ed drilling cement plugs, set X tion casing wding estimated date of starting any proposed . Circulate and condition mud. t 10695'. Drilled cement plug Circulate. Washed and reamed drilling formation at 10:30 PM s of 5-1/2" 17# casing as follow f 5-1/2" 17# N-80 LT&C (3105.09' f 5-1/2" 17# L-80 LT&C (3119.37' 3460.45') of casing set at 3419'. Baffel plate set at follows: Stage 1: 1100 sacks eld 1.22, weight 14.4). PD NTINUED ON NEXT PAGE:
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS erations (Clearly state all pertinent det Washed and reamed com 10590-10695'. Hit Washed and reamed fr Circulated. TOOH. 1500'. TOOH. TIH with TD at 6:30 AM 2-20-9 17# S-95 LT&C (3108) 17# J-55 LT&C (2230) 1/2" 17# S-95 LT&C (200) 1/2" 17# S-95 LT&C (200)	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Finishe product tails, and give pertinent dates, incl firom 10415-10590' it top of cement a rom 10829-10892'. ith bit. Resumed 97. Ran 328 joint .26'); 75 joints o .59'); 76 joints o 1897.14') (Total 1 at collar set at 1 d in two stages as 2 and .3% CD32 (yi adge and belief. CO	ALTERING CASING ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ed drilling cement plugs, set X tion casing using estimated date of starting any proposed . Circulate and condition mud. t 10695'. Drilled cement plug Circulate. Washed and reamed drilling formation at 10:30 PM s of 5-1/2" 17# casing as follow f 5-1/2" 17# N-80 LT&C (3105.09' f 5-1/2" 17# L-80 LT&C (3119.37' 3460.45') of casing set at 3419'. Baffel plate set at follows: Stage 1: 1100 sacks eld 1.22, weight 14.4). PD NTINUED ON NEXT PAGE: Technician DATE Feb. 25, 1997
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS erations (Clearly state all pertinent det Washed and reamed com 10590-10695'. Hit Washed and reamed fr Circulated. TOOH. 1500'. TOOH. TIH with TD at 6:30 AM 2-20-9 17# S-95 LT&C (3108) 17# J-55 LT&C (2230) 1/2" 17# S-95 LT&C (200) 1/2" 17# S-95 LT&C (200)	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Finishe product tails, and give pertinent dates, incl firom 10415-10590' it top of cement a rom 10829-10892'. ith bit. Resumed 97. Ran 328 joint .26'); 75 joints o .59'); 76 joints o 1897.14') (Total 1 at collar set at 1 d in two stages as 2 and .3% CD32 (yi adge and belief. CO	ALTERING CASING ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ed drilling cement plugs, set X tion casing wding estimated date of starting any proposed . Circulate and condition mud. t 10695'. Drilled cement plug Circulate. Washed and reamed drilling formation at 10:30 PM s of 5-1/2" 17# casing as follow f 5-1/2" 17# N-80 LT&C (3105.09' f 5-1/2" 17# L-80 LT&C (3119.37' 3460.45') of casing set at 3419'. Baffel plate set at follows: Stage 1: 1100 sacks eld 1.22, weight 14.4). PD NTINUED ON NEXT PAGE:

÷