

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01910
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3931
7. Lease Name or Unit Agreement Name Cities Service AQP State
8. Well No. 1
9. Pool name or Wildcat Undesignated Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line
Section 13 Township 16S Range 34E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4085' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Re-entry</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-29-96 - Dig out cellar. Weld on 11" 5000 psi wellhead. Set and tested anchors and markers. Moved in and rigged up pulling unit. Installed BOP. NOTE: 4-1/2" dry hole marker cemented inside 8-5/8" casing.

12-30-96 - Prep to wash over dry hole marker. NOTE: Notified Sylvia w/OCD-Hobbs of commencing re-entry operations.

1-1-97 - Washing over 4-1/2" stub. TIH with 3-7/8" bit and began re-entry operations at 8:30 AM 12-30-96. Drilled cement out of 4-1/2" stub. Fell out of cement at 6-1/2'. Lost returns. Pumped 10 bbls and regained full returns. Laid down bit. Picked up 7" notched shoe. Washed over outside of 4-1/2" stub. Made 1-1/2'. Laid down shoe. Spear 4-1/2" stub. Pulled 40000#. Would not move. Laid down spear. Picked up 2" shoe. Washover stub. Have made a total of 2' on outside of 4-1/2" stub.

1-1-97 - Shut down for New Years Day. Washed over 4-1/2" stub with notched shoe. TOOH and picked up shoe with smooth OD and kutrite on bottom. Washed 2'. TOOH with 6' long piece of 4-1/2" pipe. Break down washover assembly. Picked up 7-7/8" mill tooth bit,

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations' Technician DATE Jan. 3, 1997
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
DATE
TITLE

JAN 08 1997

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

7231 10 7AL

