

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name Kemnitz Wolfcamp Unit
2. Name of Operator Tenneco Oil Company		8. Farm or Lease Name Kemnitz Wolfcamp
3. Address of Operator 7990 IH 10 West, San Antonio, TX 78230		9. Well No. 6
4. Location of Well UNIT LETTER <u>M</u> <u>536</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM <u>South</u> LINE, SECTION <u>19</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Kemnitz Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Clean out well to PBTD. Perforate 10,718' to 10,744' with a 4" casing gun loaded with 2 JSPF. Acidize 10,718' to 10,744'. Swab back load. Move-in and rig-up equipment. Put well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert A. Mattue TITLE Production Engineering Super. DATE August 8, 1984

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE \_\_\_\_\_

DATE AUG 14 1984

CONDITIONS OF APPROVAL, IF ANY: