ENERGY AND MINERALS DEPARTMEN	NT	
we. of Corice Receives	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	5
JANTA FE	SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78
FILE	SALLATE, NEW MEXICO 87501	
U.3.G.3.		Sa. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Off 6 Gas Lease No.
	A NOTICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. DR FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
I. OIL X GAB .	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Hame
Marathon Oil Compa		
3. Address of Operator		State S. A.
P. O. Box 2409	Hobbs, New Mexico 88240	9. Well No.
I. Location of Well	nobbs, New Mexico 00240	2
		10. Field and Pool, or Wildcat
UNIT LETTER H 198	30 FEET FROM THE NORTH LINE AND 660 FE	Kemnitz Lower Wolfcamp
THE East LINE, SECTION	20 TOWNSHIP 165 RANGE 3'E	_ NMPM. ()
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	KB 4140', GL 4123'	Lea
Check Ap NOTICE OF INT	PPROPRIATE Box To Indicate Nature of Notice, Report ENTION TO: SUBSEC	OF Other Data
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	0THER	
OTHER		

January 17, 1985 rigged up a pulling unit, pulled out of the hole with the rods and pump. Installed the BOP's and released the tubing and pulled out of the hole with the tubing. Went in the hole with a Halliburton Retrievable Bridge Plug and RTTS packer. Set the RBP at 10,527' and tested the RBP to 1500 psi and held okay. Started testing the casing to 1500 psi by moving the RTTS packer. Found the casing leak to be between 9166' - 9197'. Pumped into the leak at 2 BPM at 800 psi. Set the RTTS packer at 8547' and squeezed the leak in the casing with 150 sacks of Class "H" neat cement. Staged last 3 barrels at 15 minute intervals at 1/2 barrel intervals per time. Final squeeze pressure 3650 psi. Pulled 2 stands and repressured to 3000 psi. Left cement over night. Bled pressure off, released the RTTS packer and pulled out of the hole. Went in the hole with a 4 5/8" bit and 6 drill collars on 2 3/8" tubing and started drilling cement.

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	TITLE	JAN 2 8 1985
. Steven A. Pohler/ Steven a. My	wwwProduction_Engineer	DATE <u>01-23-85</u>
I hereby certify that the information above is true and complet		

RECEIVED

JAN 25 1985