STATE D	F NEW MEXICO	-		-	
ENERGY AND MI	AGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION P. O. BOX 2088				Form C-103 Revised 10-1-78
FILE U.S.O.S. LAND OFFI				Sa. Indicate Typ State X 5, State Oil 6 G	Fee 🗌
OPERATOR					mmm
U TON 00)	SUNDRY N SE THIS FORM FOR PROPOSI USE "APPLICATION I	7. Unit Agreeme	 ent Name		
1. 011 X	CAS WELL		Kemnitz Wolfcamp Unit		
	neco Oil Compan	<u>Y</u>		9. Well No.	
3. Address of Open 790	on IH 10 West, S	10			
4. Location of Wei	0 660	FEET FROM THESOL	<u>1th LINE AND 1980</u>	Kemnitz Ic	wer Wolfcamp
_	IST LINE, SECTION	20 TOWNSHIP 16	5 <u>5                                   </u>	RMPM.	
	<u>IIIIIIIIII</u>	15. Elevation (Show when 4132 ° DE		12. County Lea	
16.	Check App NOTICE OF INTE	propriate Box To Indicat ENTION TO:		port of Other Data BSEQUENT REPORT OF	F:
PERFORM REMEDIA TEMPORARILY ABA PULL OR ALTER CA OTHER	NDON .	PLUG AND ABANDON Change Plans	REMEDIAL WORK COMMENCE DRILLING OPHS CASING TEST AND CEMENT OTHER <u>Return</u> WE		ERING CASING
17. Describe Prop	cased or Completed Opera	tions (Clearly state all pertinent	details, and give pertinent dat	es, including estimated date o	f starting any proposed
RBP a 2 3/8 sprin to pu circ tubin 2. Cont: and s casin	ng leak from 771 at 10513', TOL a B" EUE 8RD tubin ing loaded casing mp through reta OK with 35 bbls ng, LD ret. PU inue RIH with tu sheared band with ng to 2000'-okay	2-43', inj. rate ind t 9380'. Well has h g, RU BOP, POOH with scraper, POOH. RU iner failed, surged to surface. Tried new cement ret and h bing and cement ret th 20 pts at 7543'. 7. Pull out and stur- 43', caught circ from m. Mix and pump 10	h 10470' tubing. R H with 5½ Arrow ceme and pressure up to to pump down tubin RIH. . Pump through ret Test tubing to 250 ng back into cement	IN With 4 3/4 bit a ent ret to 7420', a 4000 psi-no flow. g again-no flow. F with 10 BW. Set 0 psi-okay. Test 5 ret. Est. injects us after pumping 12 % Halid 9. Mix sh	and 5½" attempt Reversed POOH with retainer 5½" N80 ion in 2 BFW wrry

- heavy at 15.3 ppg, circ. 10 bbls. through casing leak. SI casing annulus. Pump 2 bbls till tubing pressure reached 1000 psi, SD 10 min. TP held at 950 psi. Pump 1 ½ bbls till TP reached 1050, SD 5 min, held okay. Annulus pressure held at 500 psi. PU 10', rev circ tubing clean. POOH with tubing and stinger.
- PU 10', rev circ tubing clean. Foon with tubing and stringer.
  3: WOC 27 hours. PU and RIH with 4½" skirted insert bit, 8 DC at 800# each and 2 3/8", 8RD EUE N-80 4.7#/ft. tubing. Tagged 5½" cement retainer at 7525'. Drilled out cement stringers to 7540'. Drilled out cement retainer in 2½ hours with 6 jts. on bit cont. \*(Cont'd on back)\*

18. I hereby certify that the information above is true and complet	te to the best of my knowledge and belief.		
Nolan A Matter	TITLE Prod. Engr. Supv.	DATE_	February 22, 1984
DISTRICT I SUPERVISOR	" TITLE	DATE .	MAR 1 1984

## 3. (Cont'd)

drilling to 7585' circ. Bottoms up RD. Swibel and drained lines.

- 4. POOH with 10553' 2-3/8" 4.7 ppf N-80 8RD tubing. RU Armadillo, FL at 8770', run CCL. Made run to perf Lower Wolfcamp, 2-10' guns, 3-1/8" diameter at 2 jspf, 41 shots from 10670-10690. Made 2nd run with 2-6' guns, select fire, 2 jspf, 13 shots, 10350-54' and 10514-18'. Third run, 3-10' guns, 2 jspf, 61 shots 10600-630. Fourth run, 2-10' guns, 2 jspf, 1-10' gun, 21 shots 10640-50'. RDWL. PU 5½" 17# Baker Model R double grip packer and 10100' 2 -3/8" tubing. Set packer with 8 pts compression. Load annulus with 2% KCL, test to 500 psi, okay. RU swab, swab 4 BO and 24 BW, strong gas flow, well was dead prior to perfs. RU pump truck to tubing, RU backside Pump, pump 2000 gal 15% HCL, 500 gal gelled brine with 400 lbs. diverting agent- 30% Benzoic Acid and 70% rock salt in 4 stages, system included 5 gal/1000 gal Western SR 2 1 ½ gal/1000 friction reducer, 1 gal/1000 de-emulsifier and 40 lbs. citric acid. Pump 1st stage at 5.2 bpm, diversion pressure at 300 psi, pump 2nd stage at 8.3 pbm, diversion pressure at 1800 psi, 3rd stage 8 bpm 2600 psi, pump flush 9.2 pbm 3200 psi. ISIP 0. Average pump pressure 1000 psi at 8 bpm. Wait 30 minutes. RU swab, swab 20 BO, 60 BW. Average oil cut on last run-20% strong gas blow. Fl constant at 8400'.
- 5. Put well on production.

RECEIVED FEB 29 1984 HOULES CITACE