

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name Kemnitz Wolfcamp Unit
3. Address of Operator 6800 Park Ten Blvd., Suite 200 North San Antonio, Texas 78213	9. Well No. 31
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Kemnitz Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Put well on production</u>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU. Install BOP.
2. Pull existing gas lift string.
3. GIH w/2-3/8" and 2-7/8" tbg. Set tbg. anchor.
4. GIH w/1", 7/8", 3/4" and 5/8" rod string and pump.
5. RDPU and BOP.
6. Move in API size 456 pumping unit.
7. GIH PU tbg. rods & acidize.
8. GIH w/tbg. rods & pump.
9. Put well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert A. Matthew TITLE Production Engineering Supv. DATE July 13, 1982

Orig. Signed by
Les Clements
Oil & Gas Insp.

JUL 19 1982

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 19 1982

F. B. I.
HOBBS OFFICE