

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-10069

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Morris R. Antweil	8. Farm or Lease Name New Mexico "BB" State
3. Address of Operator Box 2010, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>22</u> TOWNSHIP <u>16-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat Townsend Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4109' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned as follows:

Spotted 25 sx cement plug across perforations 10,713' - 10,751',
Cut and pulled 5900' - 5-1/2" casing,
Spotted 25 sx cement plug across 5-1/2" casing stub @ 5900',
Spotted 25 sx cement plug across 8-5/8" casing shoe @ 4640',
Cut and pulled 500' 8-5/8" casing,
Spotted 25 sx. cement plug across 8-5/8" casing stub @ 500',
Spotted 25 sx. cement plug across 11-3/4" casing shoe @ 348',
Spotted 10 sx surface plug w/marker.
Hole was loaded with mud laden fluid
Plugged and abandoned 6 Feb. 69..

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R M Williams</u>	TITLE <u>Agent</u>	DATE <u>2-7-69</u>
APPROVED BY <u>John W. Remyer</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		