

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-1387	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Tenneco Oil Company		Kemnitz Wolfcamp Unit
3. Address of Operator		9. Well No.
6800 Park Ten Blvd., Suite 200 N., San Antonio, Texas 78213		25
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM <u>East</u> THE <u>29</u> LINE, SECTION <u>16S</u> TOWNSHIP <u>34E</u> RANGE <u>34E</u> N.M.P.M.		Kemnitz Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4121' GR		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Re-perforate & Acidize</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP @ 10685
- 2) Ran radioactive injection profile on perfs @ 10656-62 10668-69 and found no channel behind pipe.
- 3) Drilled out CIBP
- 4) Returned well to production

NOTE: Due to perforations @ 10656-62 being opened - reperforating was not performed.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>May Hall</u>	TITLE <u>Production Analyst</u>	DATE <u>June 5, 1980</u>
APPROVED BY <u>Jerry Sauer</u>	TITLE <u></u>	DATE <u>JUN 9 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		