

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01945
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E9538
7. Lease Name or Unit Agreement Name	
Kemnitz Wolfcamp Unit	
8. Well No.	30
9. Pool name or Wildcat	
Kemnitz Lower Wolfcamp	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator FINA OIL AND CHEMICAL COMPANY
3. Address of Operator P.O. BOX 10887 Midland, TX. 79702	4. Well Location Unit Letter <u>I</u> : <u>193D</u> Feet From The <u>1980 S</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>30</u> Township <u>16-S</u> Range <u>34-E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4132 GR</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Set 5½ CIBP W 10,230', cap w/35' cement
- (2) Load hole w/mud
- (3) Cut 5½ casing @ 6481', pull out of hole
- (4) Spot 98 sacks cement @ 7230, bring cement up to 6431', W.O.C. cover 5½ stub tag cement top @ 6425
- (5) Spot 35 sacks cement plug @ 4600', W.O.C., tag plug @ 4444'
- (6) Spot 30 sacks cement plug @ 1750'
- (7) Spot 30 sacks cement plug @ 400'
- (8) Spot 15 sacks cement plug @ surface, set P&A marker (4-6-94)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Julia Blue TITLE Tech I DATE 4-4-94  
TYPE OR PRINT NAME Julia Blue TELEPHONE NO. (915) 337-1975

(This space for State Use)

APPROVED BY Larry W. Hill TITLE \_\_\_\_\_ DATE FEB 15 1994

CONDITIONS OF APPROVAL, IF ANY: