

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Kennitz Wolfcamp Unit
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name Kennitz Wolfcamp
3. Address of Operator 7990 IH 10 West, San Antonio, TX 78230	9. Well No. 30
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Kennitz Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4141 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out fill from 9,000' to 10,926'. Set RBP at 10,400'. Acidize perforations at 10,288' to 10,295'. Swab back load. Lower pump from 9,000' to 10,850'. Return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert G. Matthe TITLE Production Engineering Supervisor DATE August 8, 1984

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR  
APPROVED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE AUG 14 1984

CONDITIONS OF APPROVAL, IF ANY: