

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-02696
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Daisy Chambers
8. Well No.	1
9. Pool name or Wildcat	Townsend Permo (Upper Penn)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	DF 3973, KB 3974

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Devon Energy Corp.
3. Address of Operator 20 N. Broadway, Suite 1500 Oklahoma City, OK 73102	4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line
5. Section 26 Township 15S Range 35E NMPM Lea County	6. Pool name or Wildcat Townsend Permo (Upper Penn)
7. Elevation (Show whether DF, RKB, RT, GR, etc.) DF 3973, KB 3974	8. Well No. 1

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) - SEE RULE 1103.

- 1) 12/10-Co Rep NNMOC Gary Wink
- 2) 12/14-Set 5 1/2" CIBP on w/1 @ 9900'
- 3) 12/16-Mix mud @ circ hole w/MLF
- 4) 12/16-Spot 25 sxs cmt "H", 990-9675
- 5) 12/17-Cut & pull 7000' 5 1/2" csg
- 6) 12/21-Spot 35 sxs "H" cmt w/2% Cacl @ 7050, WOC, tag TOC @ 6948.
- 7) 12/21-Spot 35 sxs cmt 6345-6245. No need to tag as per Billy P.
- 8) 12/21-Spot 35 sxs "C" cmt @ 4784'. Tag TOC @ 4681 on 12/22
- 9) 12/22-Spot 35 sxs "C" cmt @ 2050-1944, no need to tag as per OCD Billy P.
- 10) 12/22-Perf @ 419'. Pressure up on perfs.
- 11) 12/22-Perf @ 380', -Sqz 65 sxs "C" cmt down 9-5/8" csg thru perfs @ 1 bpm @ 1000 psi.  
Displace TOC to 300'. SIP @ 300 psi. Tag TOC w/tbg @ 300' on 12/23/99
- 12) Circ 20 sxs "C" cmt 60' - surface.
- 13) Cut wellhead. Install DHM and backfill cellar and pit on 12/27/99

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Area Manager DATE 12/29/99  
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 915/570-0646

(This space for State Use)

APPROVED BY Billy E. Friedman TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY:

IR GWW

N B