

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 17 3 44 PM '65

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>A-4096</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Maurice A. Machris</b>	8. Farm or Lease Name <b>State</b>
3. Address of Operator <b>11681 San Vicente Blvd. Los Angeles, California</b>	9. Well No. <b>15-2</b>
4. Location of Well UNIT LETTER <b>T</b> , <b>1980</b> FEET FROM THE <b>S</b> LINE AND <b>660</b> FEET FROM THE <b>W</b> LINE, SECTION <b>2</b> TOWNSHIP <b>16S</b> RANGE <b>35E</b> NMPM.	10. Field and Pool, or Wildcat <b>Townsend</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot a 25 sx plug to cover all perforations
2. Load hole w/mud laden fluid
3. Spot a 25 sx plug at stub of 5 1/2" casing
4. Spot a 25 sx plug at 8076'
5. Spot a 25 sx plug at 7337'
6. Spot a 25 sx plug at 6180'
7. Spot a 25 sx plug at base of 8 5/8"
8. Spot a 10 sx plug in top & erect a regulation marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

**Hobbs Pipe & Supply, Agent for M.A. Machris**

SIGNED D. Miller TITLE \_\_\_\_\_ DATE 8-16-65

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: