

COPIES RECEIVED		
DISTRIBUTION		
DATE		
BY		
OFFICE		
RATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 17 3 44 PM '65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 2716 A
7. Unit Agreement Name
8. Farm or Lease Name State
9. Well No. 32-3
10. Field and Pool, or Wildcat Townsend-Wolfcamp
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator M.A. Nachris		
Address of Operator 11681 San Vicente Blvd. Los Angeles, Calif.		
Location of Well UNIT LIEFER N 1980 FEET FROM THE N LINE AND 1980 FEET FROM THE E LINE, SECTION 3 TOWNSHIP 16S RANGE 35E NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot a 25 sx plug to cover all perforations
2. Load hole w/mud laden fluid
3. Spot a 25 sx plug at stub of 5 1/2" casing
4. Spot a 25 sx plug at 8076'
5. Spot a 25 sx plug at 7337'
6. Spot a 25 sx plug at 6180'
7. Spot a 25 sx plug at base of 8 5/8"
8. Spot a 25 sx plug at stub of 8 5/8"
9. Spot a 25 sx plug at base of 13 3/8"
10. Spot a 10 sx plug at top & erect a regulation marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Jobbs Pipe & Supply, Agent for M.A. Nachris

SIGNED [Signature] TITLE _____ DATE 8-16-65

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: