

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No.
1. OIL WELL ☐ GAS WELL ☐ OTHER- P&A 2. Name of Operator AMOCO PRODUCTION COMPANY 3. Address of Operator BOX 367, ANDREWS, TEXAS 79714 4. Location of Well UNIT LETTER R 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 4 TOWNSHIP 16-S RANGE 35E NMPM.	7. Unit Agreement Name 8. Farm or Lease Name STATE 2 9. Well No. 1 10. Field and Pool, or Wildcat TOWNSEND-WOLFCAMP	
15. Elevation (Show whether DF, RT, GR, etc.) 4034' R.D.B.	12. County LEA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER ☒ Re-Enter P&A well Salvage Casing & RE PLUG & ABANDON.		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was P&A 4-20-70 in such a manner to permit re-entry. Further evaluations have been concluded with no further use of hole contemplated.

Propose to re-enter; salvage casing & P&A as follows.

- Existing Plug @ 9650 will be maintained*
 - Cut & Pull 7" Casing from free point (Est above 8400);*
 - Spot 40 sd (100') plug in + out of 7" stub.*
 - " 60 sd (100') 8020-7920 (TABC) if casing not pulled above 7920'.*
 - " 60 sd (100') 6210-6110 (T 610R)*
 - " 45 3x In & Out of 9 3/8" CSA 4600'. (4650-4550)*
 - Shoot & pull 9 3/8" Csg from free point. (Est T CMT 2175')*
 - Spot 100' (60 5x) plug in & out of stub*
 - " " (1840-1740) (T-ANH 1790)*
 - " " (75 5x) in + out of 13 3/8" Csg @ 355'*
 - " 105x @ surface & erect P&A marker*
- All intervals to be filled w/ mud.*
- Final cleanup shall be made & location levelled.*

13 3/8" CSA 355- Circ
9 3/8" " 4600/700x
7" " 10520 x 500 &
Plugs = 10560' - 10460'
= 35 5x @ 9650'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Roy R. Yorkum*

TITLE **ADMINISTRATIVE ASSISTANT**

DATE **JUN 16 1975**

042-NMCCO-11
1-DIV

APPROVED BY
1-SUP

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

1-R124