

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-02739	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-10629	
7. Lease Name or Unit Agreement Name New Mexico "F" State	
8. Well No. 1	
9. Pool name or Wildcat Townsend Permo Upper Penn	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4040' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Bison Petroleum Corporation	
3. Address of Operator 5809 S. Western Suite 200, Amarillo, Texas 79110-3607	
4. Well Location Unit Letter <u>L</u> : <u>660</u> Feet From The <u>West</u> Line and <u>3524</u> Feet From The <u>North</u> Line Section <u>4</u> Township <u>16S</u> Range <u>35E</u> NMPM Lea County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input checked="" type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-15-93 Pull rods & tbg., set RBP @ 10,320'.
Load hole and perf. 10,198-10,210' OA
w/2 SPF. RIH w/tbg. and set pkr @ 10,100'.
Acidize perfs. w/1500 gal 15% HCl.

11-16-93 Swab 44 BLW w/tr oil & gas. Acidize w/2000 gal 20% HCl.

11-17-93 Swab 88 BLW

11-18-93 Swab 80 BLW w/tr oil & gas. Release pkr & RBP and pull tbg.

11-19-93 SD wind

11-20-93 Run tbg. and rods and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bruce O. Barthel TITLE President DATE 11-23-93
TYPE OR PRINT NAME Bruce O. Barthel

TELEPHONE NO. 806/358-0181

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 29 1993

CONDITIONS OF APPROVAL, IF ANY: