## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

instructions in the Rules and Regu		Indicate Nature of Report	by Checking Bel	0 <b>w</b>	
REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF CASING SHUT-OFI	OF TEST	REPORT ON REPAIRING WELL	
REPORT ON RESULT DF PLUGGING WELL	x	REPORT ON RECOMPTOPERATION	LETION	REPORT ON (Other)	
		November 2	22, 1954	liobbe New	Mext co
Following is a report on the					
Humble Oil & Hefining (Company of	COmpan or Operator)	7	Hulde	A. Townsend (Lease)	***************************************
Les County Casing Pul	lers	, Wc	ll No <b>2</b>	in the 55 1/4 56 1/4	of Sec
165 , R. 356 , NMPM.,.	-nosbia	Pennsylvanian	Pool,	Lea	County
he Dates of this work were as folow					
otice of intention to do the work (					
`	, , ,		94 OII		······
			(	Cross out incorrect words)	, <b>.</b> . ,
DE n 10-30-54 attempted of plug in place.	(was) (was) TAILED A to spot 10-31-	control obtained.  CCOUNT OF WORK DON  plug from 10,751 t	E AND RESUL	rs obtained th 25 sacks coment.	Pailed to
nd approval of the proposed plan (  DE   n 10-30-54 attempted (  et plug in place. on   ive days fishing for potted plug from 10,6   nd piled 100 joints on	to spot 10-31-9 50 to 10	count of work don plug from 10,751 t stuck gauge ring ing and junk basket ),450 with 25 sacks	E AND RESULE  O 10,550 will  and pilled  On 11-6-  coment. C	TS OBTAINED th 25 sacks coment. wire line out of soci 54 went to top of figure 5-1/2-inch casing	Pailed to cet. Spent in and at 4995
on 10-30-54 attempted to 10-30-54 attempted	to spot 10-31-; sauge r: 50 to 10 asing.	count of work don plug from 10,751 to the stuck gauge ring ing and junk basket 1,450 with 25 sacks Spotted plug from th 25 sacks coment.	e AND RESULT OF 10,550 with and palled comment.	TS OBTAINED th 25 sacks coment. wire line out of soci 54 went to top of figure 5-1/2-inch casing	Failed to cet. Spent in and at 4995!
in 10-30-54 attempted of the proposed plan (on 10-30-54 attempted of the plag in place. On ive days fishing for potted plag from 10,60 and piled 100 joints on ed plag from 4224 to itself.	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	ccount of work don plug from 10,751 t 54 stuck gauge ring ing and junk basket 1,450 with 25 sacks Spotted plug from th 25 sacks coment.	e AND RESULE of 10,550 with and pilled of 11-6-coment. Coment.	TS OBTAINED  th 25 sacks coment. wire line out of soci 54 went to top of fig  tt 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s	Failed to set. Spent sh and at 49951 at. Spot- sacks cement
on 10-30-54 attempted of the proposed plan (on 10-30-54 attempted of the plag in place. On ive days fishing for potted plag from 10,60 and piled 100 joints on the plag from 4224 to itself.	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	ccount of work don plug from 10,751 t 54 stuck gauge ring ing and junk basket 1,450 with 25 sacks Spotted plug from th 25 sacks coment.	e AND RESULE of 10,550 with and pilled of 11-6-coment. Coment.	TS OBTAINED  th 25 sacks coment. wire line out of soci 54 went to top of fig  tt 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s	Failed to set. Spent sh and at 49951 at. Spot- sacks cemen
on 10-30-54 attempted on 10-30-54 attempted of the plug in place. On live days fishing for potted plug from 10,60 and piled 100 joints on the plug from 4224 to filled intervals between	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	ccount of work don plug from 10,751 t 54 stuck gauge ring ing and junk basket 1,450 with 25 sacks Spotted plug from th 25 sacks coment.	e AND RESULE of 10,550 with and pilled of 11-6-coment. Coment.	TS OBTAINED  th 25 sacks coment. wire line out of soci 54 went to top of fig  tt 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s	Failed to set. Spent sh and at 49951 at. Spot- sacks cemen
on 10-30-54 attempted of the proposed plan (on 10-30-54 attempted of the plag in place. On ive days fishing for potted plag from 10,60 and piled 100 joints on the plag from 4224 to itself.	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	ccount of work don plug from 10,751 t 54 stuck gauge ring ing and junk basket 1,450 with 25 sacks Spotted plug from th 25 sacks coment.	e AND RESULE of 10,550 with and pilled of 11-6-coment. Coment.	TS OBTAINED  th 25 sacks coment. wire line out of soci 54 went to top of fig  tt 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s	Failed to set. Spent sh and at 49951 at. Spot- sacks cemen
nd approval of the proposed plan (  DE in 10-30-54 attempted (  et plug in place. on ive days fishing for potted plug from 10,6 and piled 100 joints on ed plug from 4224 to itself.	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	CCOUNT OF WORK DON plug from 10,751 t the stuck gauge ring ing and junk basket 0,450 with 25 sacks Spotted plug from th 25 sacks coment. I with mud laden fluctured location in	e AND RESULT  o 10,550 with and palled  on 11-6-  comment. 0  5035 to 489  Plugged to aid.  n accordance	TS OBTAINED  th 25 sacks coment. wire line out of soci 54 went to top of fig  tt 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s	Failed to set. Spent sh and at 4995 at. Spot- sacks cement
DE n 10-30-54 attempted of plug in place. On ive days fishing for potted plug from 10,6 and piled 100 joints or od plug from 4224 to its laced marker and clear incessed by Amasel Minessed by Miness	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	CCOUNT OF WORK DON plug from 10,751 t the stuck gauge ring ing and junk basket ),450 with 25 sacks Spotted plug from th 25 sacks coment.  with mud laden flu leveled location i	E AND RESULE  10 10,550 will  2 and pilled  3 coment. C  5035 to 489  Plugged t  Bid.  n accordance  scining Company)  ereby certify that	rs Obtained  th 25 sacks coment.  wire line out of soci 54 went to top of first 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s  with New Mexico res  cany	Failed to set. Spent sh and at 4995! It. Spot- sacks cemen sulations.
DE n 10-30-54 attempted of plug in place. On ive days fishing for potted plug from 10,6 and piled 100 joints or od plug from 4224 to its laced marker and clear incessed by Amasel Minessed by Miness	to spot 10-31-9 gauge ri 50 to 10 asing. 4610 with	CCOUNT OF WORK DON plug from 10,751 t the stuck gauge ring ing and junk basket ),450 with 25 sacks Spotted plug from th 25 sacks coment.  with mud laden flu leveled location i	e AND RESULE  o 10,550 wi and galled  on 11-6- coment. 0 5035 to 489 Plugged t  uid.  n accordance	rs Obtained  th 25 sacks coment.  wire line out of soci 54 went to top of first 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s  with New Mexico res  cany	Pailed to set. Spent h and at 49951 ht. Spot- sacks cemen gulations.
DE n 10-30-54 attempted of plug in place. On ive days fishing for potted plug from 10,6 and piled 100 joints on plug from 4224 to its like intervals between laced marker and clear (Name of plug from 10,6 and plug from 10,6	to spot 10-31- 50 to 16 150 to 16 1610 with 16	CCOUNT OF WORK DON plug from 10,751 t  Live stuck gauge ring ing and junk basket  1,450 with 25 sacks Spotted plug from th 25 sacks coment.  With mud laden fluction in  Leveled location in  Company SSION  I he to t	ereby certify that the best of my known.	rs Obtained  th 25 sacks coment.  wire line out of soci 54 went to top of first 5-1/2-inch casing 5 with 25 sacks comen  op of casing with 5 s  with New Mexico res  cany	Pailed to set. Spent th and at 49951 it. Spot- sacks cemen gulations.
in 10-30-54 attempted of the proposed plan (on 10-30-54 attempted of the plug in place. On Pive days fishing for potted plug from 10,60 and piled 100 joints of the plug from 4224 to 1111ed intervals between the proposed by Amasell Minimum proposed:  Outcome of the proposed plan (on 10-30-54 attempted plug from 4224 to 1111ed intervals between the proposed by Amasell Minimum proposed:	to spot 10-31- 50 to 16 150 to 16 1610 with 16	CCOUNT OF WORK DON plug from 10,751 t 54 stuck gauge ring ing and junk basket 0,450 with 25 sacks Spotted plug from th 25 sacks coment.  with mud laden flu leveled location in  Comp  SSION  I he Pos Rep	ereby certify that the best of my known ition	TS OBTAINED  th 25 sacks cement.  wire line out of soci 54 went to top of first  tt 5-1/2-inch casing  with 25 sacks cement  op of casing with 5 s  with New Mexico reg  the information given above is true wiedge.	Pailed to set. Spent h and at 49951 ht. Spot- sacks cemen sulations.  Superinten he and complete

jmb