

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
DEC 9 11 38 AM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Hulda A. Townsend
9. Well No. 2
10. Field and Pool, or Wildcat Midson Pennsylvania
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Sinclair Oil & Gas Company
3. Address of Operator P. O. box 1920, Hobbs, New Mexico
4. Location of Well UNIT LETTER <u>G</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4,047' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSE TO PLUG AND ABANDON AS FOLLOWS:

Present Depth 10,718 PB. Perforated 10,697-718'.
13-3/8" casing set at 299' and cement circulated to surface.
8-5/8" casing set at 4687' and cement circulated to surface.
5-1/2" casing set at 10,720' and cemented back to 10,350' from surface.

PROPOSE TO: Set cement plugs as follows; with hole full of heavy mud.
25 sacks cement across perfs. or CISP set at top of perfs. w/2 sks. cement on top.
25 sacks cement in top of 5-1/2" casing stub.
25 sacks cement at 9700' top of Wolfcamp.
25 sacks cement at 7342' top of Tubb.
25 sacks cement at 6180' top of Glorieta.
25 sacks cement in bas of 8-5/8" casing at 4687'.
10 sacks cement in top of 8-5/8" casing and cellar, install regulation dry hole marker and clean and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 12-8-65

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

Orig&2cc: OOC, Hobbs; cc: Regional Office; cc: file