

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SAITAFE                |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-85

|                                                                        |
|------------------------------------------------------------------------|
| 5a. Indicate Type of Lease                                             |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.                                           |
| E-704                                                                  |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO LIFT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                             |                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Salt Water Disposal                                                           | 7. Unit Agreement Name                              |
| 2. Name of Operator<br>Hilliard Oil & Gas, Inc.                                                                                                             | 8. Farm or Lease Name<br>State 8                    |
| 3. Address of Operator<br>3000 N. Garfield, Suite 120, Midland, TX 79701                                                                                    | 9. Well No.<br>1                                    |
| 4. Location of Well<br>UNIT LETTER A, 990 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 16- <del>5</del> RANGE 35 E N.M.P.M. | 10. Field and Pool, or Wildcat<br>Townsend Wolfcamp |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>4041' DF                                                                                                   | 12. County<br>Lea                                   |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

|                       |                          |
|-----------------------|--------------------------|
| PERFORM REMEDIAL WORK | <input type="checkbox"/> |
| TEMPORARILY ABANDON   | <input type="checkbox"/> |
| PULL OR ALTER CASING  | <input type="checkbox"/> |
| OTHER                 | <input type="checkbox"/> |

|                  |                          |
|------------------|--------------------------|
| PLUG AND ABANDON | <input type="checkbox"/> |
| CHANGE PLANS     | <input type="checkbox"/> |
| OTHER            | <input type="checkbox"/> |

|                             |                          |
|-----------------------------|--------------------------|
| REMEDIAL WORK               | <input type="checkbox"/> |
| COMMENCE DRILLING OPNS.     | <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS | <input type="checkbox"/> |
| OTHER                       | <input type="checkbox"/> |

|                      |                                     |
|----------------------|-------------------------------------|
| ALTERING CASING      | <input type="checkbox"/>            |
| PLUG AND ABANDONMENT | <input checked="" type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Plugged 1-15-82.

- MIRU R&O Well Service. POH w/tubing and packer.
- Set cement retainer @6050', squeezed w/450 sx Class "H" w/2 HR-5, tagged top of cement inside 5½" casing @ 5297'.
- Circulate hole with 10# gelled brine.
- Weld on lift nipple, found 5½ casing free @ 5200', made chemical cut @ 5200'.
- POH laying down 5½" casing.
- WIH w/2 3/8" tubing to 5250'. RU Howco, pumped 50 sx Class "C" Neat. POH w/10 stands. SI.
- WIH, tagged top of 5½" stub plug @ 5050'. POH set 40 sx Class "C" plug @ 4700'-4550', 40 sx Class "C" Neat @ 1650'-1500'.
- Cut off 8 5/8" casing 40" below GL. Spot 10 sx cement in surface, weld plate on 8 5/8" & install P&A marker, clean-up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John O. Forsyth

TITLE Senior Production Engineer

DATE January 22, 1982

APPROVED BY Eddie W. Dean

TITLE OIL & GAS INSPECTOR

DATE MAR 10 1982

CONDITIONS OF APPROVAL, IF ANY: