

CONSERVATION DIVISION

P. O. BOX 2038

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒	GAS WELL ☐	OTHER ☐	7. Unit Agreement Name
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name Hulda Townsend
Address of Operator P.O. Box 670 Hobbs, NM 88240			9. Well No. 1
Location of Well UNIT LETTER J 2310 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 16S RANGE 35E N.M.P.M.			10. Field and Pool, or Whichever Townsend Permo Penn
11. Elevation (Show whether DF, RT, GR, etc.) 4030			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
PORABLY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
THAT ☐		OTHER rpr csg, add perfs, acdz ☒	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 10,660 PB: 10,635

Work performed: 2-6-88 through 2-16-88

POOH w/rods and pump. TIH to 10,231, set RBP, test RBP to 1000psi,ok. Pump 150bbbls at 5 BPM, did not load. PUH to 8340, set pkr test to 600 psi, held. PUH to 6480, press tbq to 600psi, held, rlse pkr, PUH to 5860, set pkr, pump down tbq. Load ann. test to 600psi, ok, TIH to 6070. Set pkr, pump down tbq, press to 600psi, held, relse pkr, spot 2 sk sand on RBP. TIH w/ cmt rtmr to 5855'. Load and test annulus to 500psi, establish inj. rate at 3 BPM at 800psi, Mix and pump 425sx Cl H neat cmt at 15.6 ppg. Displacd w/ 33bbbls FW. Reverse out 5sx cmt. WOC 22 hrs. Est. circ. DO rtmr at 5845, do cmt f/5847 to 6017. Press test sqz to 300psi, failed leaked off at WH, tighten up same and retest, lost 100psi in 2 min. Swab, Change out o-ring seal, NU BOP, RIH w/ pkr, set at 60', tst ann from 60' to surf, 500psi for 5 min, ok. Tst csg/sqz for 5 min., ok. Release pkr, wash sand f/10205 to 10,220'. Run GR,CCL. RIH w/ 4" csg gun, perf 10,466 -70(8 shots) and 10378-82 2 SPF, 180°phsd, prem charge total 16 holes.Spot 100 gallons 20% NEFE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<u>M. E. Abin</u>		TITLE	DATE
ORIGINAL SIGNED BY JERRY EDGEMAN			
DISTRICT I SUPERVISOR			
ED BY		TITLE	DATE FEB 24 1988
ITIONS OF APPROVAL, IF ANY:			

HOBBS OFFICE

FEB 24 1988

RECEIVED