

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02764
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Hulda A. Townsend
8. Well No. 5
9. Pool name or Wildcat Townsend Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Re-entry	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4037.5 DF
Name of Operator JFG Enterprise	
Address of Operator PO BOX 100, Artesia, NM 88210	
Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The East Line Section 9 Township 16S Range 35E NMPM Lea County	

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05-04-94 Re-entered & drilled cement plugs, fished junk out of hole, cleaned out to original perforations 10,386 - 10,448. Pumped 1000 gal 15% MCA. Est. rate 3-1/2 BPM @ 2800#. ISIP 1500# 1 min. vacuum.

05-23-94 POH w/packer. Run tubing & rods & pump.

05-24-94 Start pumping in frac tank.

05-25-94 Lay flowline. Tie into tank battery. Pumping 8 BO 12 BW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J.T. Jackson TITLE Partner DATE 4-19-95

TYPE OR PRINT NAME J.T. Jackson TELEPHONE NO 505-746-9680

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APR 25 1995

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OFFICE

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C. 20535