## NEW MEXICO CIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HUBBS OFFICE O.C.C.

MISCELLANEOUS NOTICES Submit this notice in TRIPLICATE to the District Office, Gil Concervation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Notano el Netico by Genician Relay

Notice of Intention to Change Plans	NOTICE OF INTENTION TO TEMPORARILY ABANDON V		Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squezze	Noticz of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	
DIL CONSERVATION COMMIS Santa Fe, New Mexico	110005, 11	ew Mexico	7-27- (Date)	64
Gentlemen:	(Plac	ce)	(Date)	
Following is a Notice of Inten (Company SW 16 NE 16 of Sec	ntion to do certain work as described 1 H. A. To or Operator) 	wnsend	Well No. 6	G in
(40-acre Subdivision) Lea	, T, <b>K</b>	<u>,</u> NMPM		Pool
	FULL DETAILS OF PROP			
1. Run radioactio	FOLLOW INSTRUCTIONS IN THE			e to 2300# r
1. Run radioaction 2. Acidize with the				e to 2300# n
1. Run radioaction 2. Acidize with the	7. – Herrianwey. 5,000 gallons N.E. r			e to 2300# n
1. Run radioaction 2. Acidize with the	7. – Herrianwey. 5,000 gallons N.E. r			e to 2300# n
1. Run radioaction 2. Acidize with the	7. – Herrianwey. 5,000 gallons N.E. r			e to 2300# n
1. Run radioaction 2. Acidize with the	7. – Herrianwey. 5,000 gallons N.E. r			e to 2300# n
1. Run radioaction 2. Acidize with the	7. – Herrianwey. 5,000 gallons N.E. r			e to 2300# n
1. Run radioaction 2. Acidize with the	7. – Herrianwey. 5,000 gallons N.E. r			e to 2300# n
<ol> <li>Run radioaction</li> <li>Acidize with a second s</li></ol>	, ooo gallons N.E. r pump and test.	etarded HC		
<ol> <li>Run radioaction</li> <li>Acidize with 1</li> <li>Place well on</li> </ol>	, ooo gallons N.E. r pump and test.	etarded HC	L. Hold pressur	
<ol> <li>Run radioaction</li> <li>Acidize with a second s</li></ol>		etarded HC Humb	L. Hold pressur	
<ol> <li>Run radioaction</li> <li>Acidize with 1</li> <li>Place well on</li> </ol> Approved Except as follows:	, , , , , , , , , , , , , ,	etarded HC Humb	L. Hold pressur le Oil & Refinin Company or Operator	g Co.
1. Run radioaction 2. Acidize with the	5.000 gallons N.E. r pump and test.	etarded HC Humb Sy	L. Hold pressur le Oil & Refinin ((Company or Operator gent	ell to:
1. Run radioaction 2. Acidize with 3. Place well on Approved Except as follows: Approved OIL CONSERVATION COMMIN	5.000 gallons N.E. r pump and test.	etarded HC Humb Position A Send Humbl	L. Hold pressur le Oil & Refinin (Company or Operator (Company or Operator gent Communications regarding w	ell to: