

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

LAND CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Exxon Corp. 3. Address of Operator P. O. Box 1600, Midland, TX 79702 4. Location of Well UNIT LETTER <u>K</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>9</u> TOWNSHIP <u>16 S</u> RANGE <u>35 E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4024 DF	7. Unit Agreement Name 8. Farm or Lease Name H.A. Townsend A/C-2 9. Well No. 7 10. Field and Pool, or Wildcat Townsend Permo Upper Penn 12. County Lea
--	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Filed to complete records</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

5-15-84 Set Cmt. retainer @ 7050'. Sqz'd w/450 sx CLH & 1/2#/sx cellophane.
Circulate hole w/10 PPG Brine Mud.
Spotted 20 sx plug @ 4650'.
5-19-84 Cut off 5 1/2" csg @ 3337'.
5-21-84 Spotted 30 sx plug @ 3387'.
5-22-84 Cut off 7 5/8" csg @ 1000'. Spotted 80 sx plug @ 1950'. Spotted 50 sx plug @ 1050'.
5-23-84 TIH & tagged plug @ 800'. Spotted 70 sx plug @ 500'.
5-24-84 TIH & tagged plug @ 418'. Pumped 25 more sx @ top of last plug per request of NMOCD.
Spotted 10 sx @ surface.
Cut off wellhead & weld on plate & dry hole maker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stephen Johnson TITLE Administrative Specialist DATE 5-12-88

APPROVED BY Oil & Gas Inspector TITLE Oil & Gas Inspector DATE MAY 18 1988

CONDITIONS OF APPROVAL, IF ANY:

8

DECLASSIFIED
MAY 1 1988
DCI
HOBBS OFFICE