

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

FEB 23 12 44 PM '65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Brunson & Laughlin	5. State Oil & Gas Lease No.
3. Address of Operator 600 Lidden, Apt. 44, Midland, Texas	7. Unit Agreement Name
4. Location of Well UNIT MEASUREMENT H 11 FEET FROM THE 9 LINE AND 6 FEET FROM THE 10 LINE, SECTION 10 TOWNSHIP 16 RANGE 35 NMPM.	8. Farm or Lease Name Nachris
	9. Well No. 42-10
	10. Field and Pool, or Wildcat Townsend
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- #1 - Spot a 25 sx. plug to cover perforations.
- #2 - Spot at 25 sx. plug at stub of 5-1/2" Casing.
- #3 - a 25 sx. plug at 9500'.
- #4 - a 25 sx. plug at 8100'.
- #5 - a 25 sx. plug at 7400'.
- #6 - a 25 sx. plug at 6200'.
- #7 - Spot a 25 sx. plug at 4700'.
- #8 - Spot a 10 sx. plug on top and erect 4" marker.
- #9 - Hole will be loaded with mud laden fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>D. Drisk</i></u>	TITLE Asst. Manager	DATE 2-22-65
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		