

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name STATE "AG"
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1980</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>10</u> TOWNSHIP <u>16-S</u> RANGE <u>35-E</u> N.M.P.M.	10. Field and Pool, or Wildcat TOWNSEND NOLE CAMP
15. Elevation (Show whether DF, RT, GR, etc.) 4017 R.D.B.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Physical abandonment effected 4-4-70.  
Plugged and abandoned as follows:  
Spotted 35 sq @ 10,300'. (Perfs. 10516-10610')  
" 100 sq @ 9,400'  
Shot 5 1/2" @ 7803', 7000', 6496', 6009', 5504', 5004'. 25 sq In & Out of Stub.  
Spotted 50 sq @ 4700'  
Shot 9 3/8" @ 1605', 1215', 600'. Spot 25 sq. In & Out of Stub.  
Spotted 50 sq @ 385' (13 3/8" CSA 359')  
" 10 sq @ Surface & erected P.A. marker.  
Final cleanup shall be made and ground restored to contour.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE AREA SUPERINTENDENT DATE APR 29 1970

042-NMOC-1  
APPROVED BY John A. Runyan TITLE Geologist  
CONDITIONS OF APPROVAL, IF ANY:  
1- W.F. Spencer  
1- R.R.Y.  
DATE JUL 16 1970

RECEIVED

APR 30 1970

OIL CONSERVATION C. M.  
HOBBE, N. M.