

Drig Engr. MCP Drlg Supt: Resv Engr: Prod Engr: Prod Supt:

A Business Unit of Unocal

## **South Permian Asset Group** CONDITION OF HOLE

TOTAL DEPTH: 10585' ETD: 10514' KB DATUM: 13.0' Above: G.L.(4023.0)

	Townsend Field	LEASE: State "A"	WELL NO: #	4
Location			17 LLL 110. π	I
Location.	Sec 10, T-16-S R-35-E	County: Lea	State: N	ew Mexico
Survey:				
REASON FO	OR WORK: To test for a	casing integrity and or plug an	d abandon the well.	
CONDITION	OF HOLE:			

## **CASING RECORD:**

11-3/4 @ 364'. 42# H-40 ST&C Csg. Cmt'd w/450sx. Cmt Circ. 8-5/8" @ 4,666'. 32# & 28# J-55 ST&C Csg. Cmt'd w/2250sx. Circ. 5-1/2" @ 10,460'. 17# N-80 & K-55, LT&C Csg. Cmt'd w/600 sx TOC @ 7950'.

## **PERFORATIONS:**

Formation	Date	From	То	# Holes
Wolfcamp	11/23/52	10.460	10.585	open hole

TUBING DETAIL:	Tubing TAC Tubing SN sub MA TOTAL	2-7/8" 6.5# J-55 USS 8rd E 5-1/2" X 2-7/8" 2-7/8" 6.5# J-55 USS 8rd E 2-7/8" Mech 2-7/8" per'd 2-7/8" 6.5# J-55 USS 8rd E	328jts 1 10jts 1 1	10,111.77' 2.90' 308.26' 1.10' 4.00' 31.84'
				10,459.87'
	KB			15.00
	FHD			10,474.87

118 -1" rods, 142- 7/8" rods, 157- 3/4" rods. Subs are 1-8', 1-6', 1-2', 1-2'. **ROD DETAIL** 

**REGULATORY REQUIREMENTS:** Sundry Notice.