



Drig Engr:	<u>MCP</u>
Drig Supt:	
Resv Engr:	
Prod Engr:	
Prod Supt:	

South Permian Asset Group
CONDITION OF HOLE

April 10, 1997
FIELD: Townsend Field **LEASE:** State "A" **WELL NO:** #2
Location: Sec 10, T-16-S R-35-E **County:** Lea **State:** New Mexico
Survey: _____
REASON FOR WORK: To test for casing integrity and or plug and abandon the well.

CONDITION OF HOLE:

TOTAL DEPTH: 11599' **ETD:** 11355' **KB DATUM:** 13.0' **Above:** G.L.(4023.0)

CASING RECORD:

11-3/4" @ 348'. 42# H-40 ST&C Csg. Cmt'd w/450sx. Cmt Circ.
8-5/8" @ 4,710'. 32# & 28# J-55 ST&C Csg. Cmt'd w/2500sx. Circ.
5-1/2" @ 10,630'. 17# 20# N-80 & K-55, LT&C Csg. Cmt'd w/405 sx TOC @ 8270'.

PERFORATIONS:

Formation	Date	From	To	# Holes
Wolfcamp	2/11/54	10,630	11,355	open hole

TUBING DETAIL: None

ROD DETAIL

REGULATORY REQUIREMENTS: Sundry Notice.